

Basic Asset/Component Information													Financial Accounting Values				Condition / Performance and Risk Assessment Information							
Asset Number	Category	Sub-Category	Department	Location	Process	Sub-Process	System	Class of Asset	Year of Acquisition	Useful Life	Remaining Useful Life	Age	Historical Cost December 31, 2012	Accumulated Amortization December 31, 2012	Net Book Value December 31, 2012	Annual Amortization Expense	Replacement Cost	Condition Rating	Method of Last Condition Assessment	Asset Conditions / Deficiencies	Probability of Failure	Consequence of Failure	Risk / Criticality	Critical Maintenance Activities / Immediate Replacement
													\$ 49,841	\$ 13,359	\$ 36,482	\$ -	\$ 34,893,500							
AIR-001	Mach/Equip	Hardware	Air Transportation	4599 Airport Rd	Wastewater Treatment	Sewage Lift Station	Electrical	MCC and Wiring	1990	50	27	23					\$ 30,000	4	Field Audit	Control board stuck by lightning and control card damaged, replaced 2007. Metal housing severely rusted	3.0	3.0	9.0	
AIR-002	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Sewage Lift Station	Auxiliary	Access Ladder, Floor Grates, Access Cover, Hoist	1990	50	27	23					\$ 10,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-003	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Sewage Lift Station	Pumps	Submersible Pump 1	1990	40	17	23					\$ 25,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-004	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Sewage Lift Station	Pumps	Submersible Pump 2	1990	40	17	23					\$ 25,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-005	Buildings	Structure	Air Transportation	4599 Airport Rd	Wastewater Treatment	Sewage Lift Station	Structure	Concrete Structure	1990	80	57	23					\$ 50,000	3	Field Audit	Some spalling and cracking on structure above ground level. Efflorescence on interior wall.	1.0	4.0	4.0	
AIR-006	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Sewage Lift Station	Piping and Valves	Inlet Piping	1990	80	57	23					\$ 2,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-007	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Sewage Lift Station	Piping and Valves	Force-main (800 m)	1990	80	57	23					\$ 180,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-008	Buildings	Structure	Air Transportation	4599 Airport Rd	Wastewater Treatment	Primary Clarifier	Structure	5m x 8m Fiber Glass Tank	1990	60	37	23					\$ 5,000	2	Field Audit	Good	2.0	4.0	8.0	
AIR-009	Buildings	Structure	Air Transportation	4599 Airport Rd	Wastewater Treatment	Biological Contactor	Structure	5m x 10m Fiber Glass Tank	1990	60	37	23					\$ 7,000	2	Field Audit	Good	2.0	4.0	8.0	
AIR-010	Buildings	Structure	Air Transportation	4599 Airport Rd	Wastewater Treatment	Secondary Clarifier	Structure	4m Diameter Circular Fiber Glass Tank	1990	60	37	23					\$ 5,000	2	Field Audit	Good	2.0	4.0	8.0	
AIR-011	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Biological Contactor	Auxiliary	Cover	1990	80	57	23					\$ 1,500	4	Field Audit	Severely cracked, cover not properly assembled - sealed with spray foam insulation and metal reinforcement	5.0	2.0	10.0	
AIR-012	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Secondary Clarifier	Auxiliary	Cover	1990	80	57	23					\$ 1,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-013	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Biological Contactor	HVAC	Electric Heaters (2)	1990	40	17	23					\$ 5,000	2	Field Audit	Good	3.0	2.0	6.0	
AIR-014	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Biological Contactor	Electrical	Lighting	1990	40	17	23					\$ 500	3	Field Audit	Fair	3.0	1.0	3.0	
AIR-015	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Biological Contactor	Electrical	Wiring	1990	60	37	23					\$ 10,000	2	Field Audit	Good	2.0	4.0	8.0	
AIR-016	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Biological Contactor	Auxiliary	Metal Floor Grates, Access Ladders	1990	80	57	23					\$ 6,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-017	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Biological Contactor	Process Equipment	Motor	1990	60	37	23					\$ 3,000	2	Field Audit	Good	3.0	4.0	12.0	
AIR-018	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Biological Contactor	Process Equipment	Chain Drive and Metal Cover	1990	60	37	23					\$ 3,000	2	Field Audit	Good	2.0	4.0	8.0	
AIR-019	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Biological Contactor	Process Equipment	Rotating Contactor Structure	1990	60	37	23					\$ 100,000	2	Field Audit	Good	2.0	5.0	10.0	
AIR-020	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Secondary Clarifier	Auxiliary	Metal Floor Grates, Access Ladder	1990	80	57	23					\$ 6,000	5	Field Audit	Access ladder severely corroded	4.0	3.0	12.0	Replace access ladder within 2 years
AIR-021	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Secondary Clarifier	Pumps	Sludge Pump	1990	40	17	23					\$ 1,000	2	Field Audit	Good	3.0	2.0	6.0	
AIR-022	Buildings	Structure	Air Transportation	4599 Airport Rd	Wastewater Treatment	Outlet	Structure	Outlet Structure and Piping	1990	80	57	23					\$ 10,000	2	Field Audit	Good	1.0	3.0	3.0	
AIR-023	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Primary Clarifier	Piping and Valves	Inlet Piping	1990	80	57	23					\$ 1,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-024	Mach/Equip	Hardware	Air Transportation	4599 Airport Rd	Wastewater Treatment	Wastewater Treatment	Electrical	MCC	1990	20	0	23					\$ 30,000	3	Field Audit	Fair	3.0	4.0	12.0	
AIR-025	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Wastewater Treatment	Electrical	Wiring	1990	60	37	23					\$ 5,000	5	Field Audit	Underground wiring to the secondary clarifier is b	5.0	4.0	20.0	Replace within 2 years
AIR-026	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Wastewater Treatment	Wastewater Treatment	Site	Fencing (12m x 30m)	1990	60	37	23					\$ 3,000	1	Field Audit	Good	2.0	1.0	2.0	
AIR-027	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Electrical	Diesel Fuel Storage Tank (Exterior)	1976	60	23	37					\$ 20,000	4	Field Audit	Rusting tank and supports, adjacent to "Well 2"	3.0	5.0	15.0	Remove within 1 year - relocate storage away from Well 2
AIR-028	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Structure	Pumphouse Building (Original and Addition)	1976	80	35	45					\$ 200,000	2	Field Audit	Expansion in 1976 including reservoirs 3 & 4	2.0	3.0	6.0	
AIR-029	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Structure	Pumphouse Building Roof	1976	20	0	37					\$ 50,000	4	Field Audit	Fair	2.0	3.0	6.0	
AIR-030	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Piping and Valves	Raw Water Inlet Piping (4")	1968	80	35	45					\$ 5,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-031	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Pumps	Chlorine Pump 1	2000	20	7	13					\$ 3,000	2	Field Audit	Good	5.0	3.0	15.0	Replacement of chlorination system and improvement to system control, within 3 years
AIR-032	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Pumps	Chlorine Pump 2	2000	20	7	13					\$ 3,000	2	Field Audit	Good	5.0	3.0	15.0	Replacement of chlorination system and improvement to system control, within 3 years
AIR-033	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Piping and Valves	Chlorine Piping	2000	20	7	13					\$ 500	2	Field Audit	Good	5.0	3.0	15.0	Replacement of chlorination system and improvement to system control, within 3 years
AIR-034	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Pumps	Booster Pump 1	1976	60	23	37					\$ 20,000	4	Field Audit	Severely rusted	4.0	3.0	12.0	Replace within 5 years
AIR-035	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Pumps	Booster Pump 2	1976	60	23	37					\$ 20,000	4	Field Audit	Severely rusted	4.0	3.0	12.0	Replace within 5 years
AIR-036	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Pumps	Booster Pump 1 - Motor and Drive	1976	60	23	37					\$ 5,000	4	Field Audit	Fair	4.0	3.0	12.0	Replace within 5 years
AIR-037	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Pumps	Booster Pump 2 - Motor and Drive	1976	60	23	37					\$ 5,000	4	Field Audit	Fair	4.0	3.0	12.0	Replace within 5 years
AIR-038	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Piping and Valves	Booster Pump 1 - Isolation Valves	1976	60	23	37					\$ 2,000	2	Field Audit	Good	2.0	3.0	6.0	
AIR-039	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Piping and Valves	Booster Pump 2 - Isolation Valves	1976	60	23	37					\$ 2,000	2	Field Audit	Good	2.0	3.0	6.0	
AIR-040	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Pumps	Fire Pump 1	1976	60	23	37					\$ 30,000	3	Field Audit	Fair	2.0	2.0	4.0	
AIR-041	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Pumps	Fire Pump 2	1976	60	23	37					\$ 30,000	3	Field Audit	Fair	2.0	2.0	4.0	
AIR-042	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Pumps	Fire Pump 1 - Diesel Drive	1976	60	23	37					\$ 50,000	3	Field Audit	Motor base rusting	2.0	2.0	4.0	
AIR-043	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Pumps	Fire Pump 2 - Diesel Drive	1976	60	23	37					\$ 50,000	3	Field Audit	Motor base rusting	2.0	2.0	4.0	
AIR-044	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Auxiliary	Diesel Fuel Tank 1	1976	60	23	37					\$ 2,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-045	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Auxiliary	Diesel Fuel Tank 2	1976	60	23	37					\$ 2,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-046	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	HVAC	Louvers	1976	60	23	37					\$ 1,500	2	Field Audit	Good	2.0	1.0	2.0	
AIR-047	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	HVAC	Louvre Actuator and Batteries	1976	40	3	37					\$ 1,500	3	Field Audit	Fair	3.0	1.0	3.0	
AIR-048	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	HVAC	Gas Furnace and Ductwork	2000	40	27	13					\$ 30,000	1	Field Audit	Good	2.0	2.0	4.0	
AIR-049	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Process Equipment	Pressure Vessel 1	2009	40	36	4					\$ 5,000	3	Field Audit	Rusting around vessel base	2.0	4.0	8.0	
AIR-050	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Process Equipment	Pressure Vessel 2	2009	40	36	4					\$ 5,000	3	Field Audit	Rusting around vessel base	2.0	4.0	8.0	
AIR-051	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Process Equipment	Pressure Vessel 3	2010	40	37	3					\$ 5,000	2	Field Audit	Good	2.0	4.0	8.0	
AIR-052	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Process Equipment	Pressure Vessel 4	2010	40	37	3					\$ 5,000	2	Field Audit	Good	2.0	4.0	8.0	
AIR-053	Buildings	Structure	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Structure	Reservoir 1	1968	80	35	45					\$ 340,000	2	Field Audit	Good	3.0	3.0	9.0	
AIR-054	Buildings	Structure	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Structure	Reservoir 2	1968	80	35	45					\$ 340,000	2	Field Audit	Good	3.0	3.0	9.0	
AIR-055	Buildings	Structure	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Structure	Reservoir 3	1976	80	43	37					\$ 765,000	2	Field Audit	Good	1.0	4.0	4.0	
AIR-056	Buildings	Structure	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Structure	Reservoir 4	1976	80	43	37					\$ 765,000	2	Field Audit	Good	1.0	4.0	4.0	
AIR-057	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Auxiliary	Reservoir 1 & 2 - Access Hatch	1968	80	35	45					\$ 2,000	2	Field Audit	Currently has no lock - Safety concern,	2.0	2.0	4.0	Provide a lock ASAP
AIR-058	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Auxiliary	Reservoir 3 & 4 - Access Hatch	1976	80	43	37					\$ 2,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-059	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Piping and Valves	Suction Piping (6")	1976	80	43	37					\$ 2,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-060	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Piping and Valves	Distribution Piping (4")	1968	80	35	45					\$ 8,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-061	Mach/Equip	Hardware	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Control	PLC - Fire Pump	1976	20	0	37					\$ 2,000	4	Field Audit	Good	2.0	2.0	4.0	
AIR-062	Mach/Equip	Hardware	Air Transportation	4599 Airport Rd	Water Supply	Water Pumping Station	Control	PLC - Fire Pump	1976	20	0	37					\$ 30,000	4	Field Audit	Fair	4.0	4.0	16.0	Replace within 3 years
AIR-063	Mach/Equip	Heavy	A																					



City of Timmins  
2014 Asset Management Plan  
Airport

Basic Asset/Component Information													Financial Accounting Values				Condition / Performance and Risk Assessment Information							
Asset Number	Category	Sub-Category	Department	Location	Process	Sub-Process	System	Class of Asset	Year of Acquisition	Useful Life	Remaining Useful Life	Age	Historical Cost December 31, 2012	Accumulated Amortization December 31, 2012	Net Book Value December 31, 2012	Annual Amortization Expense	Replacement Cost	Condition Rating	Method of Last Condition Assessment	Asset Conditions / Deficiencies	Probability of Failure	Consequence of Failure	Risk / Criticality	Critical Maintenance Activities / Immediate Replacement
AIR-102	Infrastructure	Road Surface	Air Transportation	4599 Airport Rd	Roads	Taxiway A	Transport	Asphalt Road Surface (5,000 m2)	2001	20	8	12					\$ 209,000	4	Field Audit	Heaving along Taxiway in line with catchbasin	4.0	3.0	12.0	Investigate if there is an abandoned pipe that has failed beneath taxiway. Dig a full depth 4 m wide trench along the failure, remove pipe if necessary and backfill to the existing taxiway specifications.
AIR-103	Infrastructure	Road Surface	Air Transportation	4599 Airport Rd	Roads	Taxiway B	Transport	Asphalt Road Surface (15,000 m2)	2001	20	8	12					\$ 627,000	3	Field Audit	Fair	2.0	2.0	4.0	
AIR-104	Infrastructure	Road Surface	Air Transportation	4599 Airport Rd	Roads	Taxiway C	Transport	Asphalt Road Surface (112,682 m2)	2001	20	8	12					\$ 5,130,000	3	Field Audit	Fair	2.0	2.0	4.0	
AIR-105	Infrastructure	Road Surface	Air Transportation	4599 Airport Rd	Roads	Ring Road	Transport	Asphalt Road Surface (6,270 m2)	2007	20	14	6					\$ 283,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-106	Infrastructure	Road Surface	Air Transportation	4599 Airport Rd	Roads	Access Road	Transport	Asphalt Road Surface (1,480 m2)	2000	20	7	13					\$ 62,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-107	Infrastructure	Road Surface	Air Transportation	4599 Airport Rd	Roads	Runway 03-12 (N/S)	Transport	South Concrete Button (6,765 m2)	1955	20	0	58					\$ 710,000	3	Field Audit	Fair	3.0	2.0	6.0	
AIR-108	Infrastructure	Road Surface	Air Transportation	4599 Airport Rd	Roads	Runway 03-12 (N/S)	Transport	North Concrete Button (6,350.8 m2)	1955	20	0	58					\$ 667,000	3	Field Audit	Fair	3.0	2.0	6.0	
AIR-109	Infrastructure	Road Surface	Air Transportation	4599 Airport Rd	Roads	Apron 1	Transport	Concrete Apron (25,794 m2)	1955	20	0	58					\$ 2,708,000	3	Field Audit	Fair	2.0	2.0	4.0	
AIR-110	Infrastructure	Road Surface	Air Transportation	4599 Airport Rd	Roads	Apron 2	Transport	Asphalt Surface (10,000m2)	2001	20	8	12					\$ 418,000	3	Field Audit	minor ponding suggesting subsurface consolidation	4.0	2.0	8.0	Add additional granulars upon next resurfacing to alleviate ponding
AIR-111	Infrastructure	Road Surface	Air Transportation	4599 Airport Rd	Roads	Parking Lot A	Transport	Asphalt Surface (10,000m2)	2012	20	19	1					\$ 418,000	1	Field Audit	Good	2.0	2.0	4.0	
AIR-112	Infrastructure	Road Surface	Air Transportation	4599 Airport Rd	Roads	Parking Lot B	Transport	Asphalt Surface (5,000m2)	2012	20	19	1					\$ 209,000	1	Field Audit	Good	2.0	2.0	4.0	
AIR-113	Infrastructure	Road Sub Surface	Air Transportation	4599 Airport Rd	Roads	Runway 03-12 (N/S)	Transport	Runway Sub Surface (74,115 m2)	1955	50	0	58					\$ 2,139,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-114	Infrastructure	Road Sub Surface	Air Transportation	4599 Airport Rd	Roads	Runway 10-28 (E/W)	Transport	Runway Sub Surface (67,140m2)	1955	50	0	58					\$ 1,938,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-115	Infrastructure	Road Sub Surface	Air Transportation	4599 Airport Rd	Roads	Taxiway A	Transport	Road Sub Surface (5,000 m2)	1955	50	0	58					\$ 144,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-116	Infrastructure	Road Sub Surface	Air Transportation	4599 Airport Rd	Roads	Taxiway B	Transport	Road Sub Surface (15,000 m2)	1955	50	0	58					\$ 433,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-117	Infrastructure	Road Sub Surface	Air Transportation	4599 Airport Rd	Roads	Taxiway C	Transport	Road Sub Surface (112,682 m2)	1955	50	0	58					\$ 3,252,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-118	Infrastructure	Road Sub Surface	Air Transportation	4599 Airport Rd	Roads	Ring Road	Transport	Road Sub Surface (6,270 m2)	2007	50	44	6					\$ 122,000	1	Field Audit	Good	2.0	2.0	4.0	
AIR-119	Infrastructure	Road Sub Surface	Air Transportation	4599 Airport Rd	Roads	Access Road	Transport	Road Sub Surface (1,480 m2)	1955	50	0	58					\$ 43,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-120	Infrastructure	Road Sub Surface	Air Transportation	4599 Airport Rd	Roads	Runway 03-12 (N/S)	Transport	South Concrete Button Sub Surface (6,765 m2)	1955	50	0	58					\$ 106,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-121	Infrastructure	Road Sub Surface	Air Transportation	4599 Airport Rd	Roads	Runway 03-12 (N/S)	Transport	North Concrete Button Sub Surface (6,350.8 m2)	1955	50	0	58					\$ 43,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-122	Infrastructure	Road Sub Surface	Air Transportation	4599 Airport Rd	Roads	Apron 1	Transport	Concrete Apron Sub Surface (25,794 m2)	1955	50	0	58					\$ 744,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-123	Infrastructure	Road Sub Surface	Air Transportation	4599 Airport Rd	Roads	Apron 2	Transport	Apron Sub Surface (10,000m2)	1955	50	0	58					\$ 289,000	2	Field Audit	Good	2.0	2.0	4.0	
AIR-124	Infrastructure	Road Sub Surface	Air Transportation	4599 Airport Rd	Roads	Parking Lot A	Transport	Parking Lot Sub Surface (10,000m2)	2012	50	49	1					\$ 195,000	1	Field Audit	Good	2.0	2.0	4.0	
AIR-125	Infrastructure	Road Sub Surface	Air Transportation	4599 Airport Rd	Roads	Parking Lot B	Transport	Parking Lot Sub Surface (5,000m2)	2012	50	49	1					\$ 97,500	1	Field Audit	Good	2.0	2.0	4.0	
AIR-126	Infrastructure	Guideways	Air Transportation	4599 Airport Rd	Roads	Parking Lot A	Guideways	Steel Guiderail (300 m)	2012	25	24	1					\$ 30,000	1	Field Audit	Good	2.0	2.0	4.0	
AIR-127	Infrastructure	Guideways	Air Transportation	4599 Airport Rd	Roads	Parking Lot B	Guideways	Steel Guiderail (300 m)	2012	25	24	1					\$ 30,000	1	Field Audit	Good	2.0	2.0	4.0	
AIR-128	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Lighting	Runway 03-12 (N/S)	Electrical	Runway Lights (76)	2001	40	28	12					\$ 152,000	2	Desktop Review	Good	3.0	2.0	6.0	
AIR-129	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Lighting	Runway 10-28 (E/W)	Electrical	Runway Lights (67)	2001	40	28	12					\$ 134,000	2	Desktop Review	Good	3.0	2.0	6.0	
AIR-130	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Lighting	Runway 03-12 (N/S)	Electrical	Continuous Burn Guide Lighting	1955	40	0	58					\$ 200,000	3	Desktop Review	Fair. Assumed condition rating	3.0	3.0	9.0	
AIR-131	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Lighting	Runway 10-28 (E/W)	Electrical	Continuous Burn Guide Lighting	1955	40	0	58					\$ 200,000	3	Desktop Review	Fair. Assumed condition rating	3.0	3.0	9.0	
AIR-132	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Lighting	Runway 03-12 (N/S)	Electrical	Strobe Guide Lighting	1955	40	0	58					\$ 300,000	3	Desktop Review	Fair. Assumed condition rating	3.0	3.0	9.0	
AIR-133	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Lighting	Runway 10-28 (E/W)	Electrical	Strobe Guide Lighting	1955	40	0	58					\$ 300,000	3	Desktop Review	Fair. Assumed condition rating	3.0	3.0	9.0	
AIR-134	Mach/Equip	Heavy	Air Transportation	4599 Airport Rd	Lighting	Electrical	Electrical	General Electrical Requirements for Light Systems	2001	60	48	12					\$ 350,000	3	Desktop Review	Fair. Assumed condition rating	3.0	4.0	12.0	
AIR-135	Mach/Equip	Software	Air Transportation	4599 Airport Rd	Lighting	Lighting	Control	Airfield Lighting Control and Monitoring System	2013	20	20	0					\$ 55,000	3	Desktop Review	Fair. Assumed condition rating	2.0	4.0	8.0	
AIR-136	Mach/Equip	Hardware	Air Transportation	4599 Airport Rd	Lighting	Lighting	Control	Constant Current Regulators	2013	20	20	0					\$ 150,000	3	Desktop Review	Fair. Assumed condition rating	2.0	4.0	8.0	
AIR-137	Site	Site	Air Transportation	4599 Airport Rd	Site	Site	Security	Fencing (14.5 km)	1955	50	0	58					\$ 300,000	3	Desktop Review	Fair. Assumed condition rating	2.0	3.0	6.0	
AIR-138	Site	Site	Air Transportation	4600 Airport Rd	Site	Electrical	Security	Security Cameras and Monitoring System	2002	20	9	11					\$ 200,000	3	Desktop Review	Fair. Assumed condition rating	2.0	4.0	8.0	
AIR-139	Mach/Equip	Hardware	Air Transportation	4621 Airport Rd				WOODSTOCK Server- PowerEdge 1400	2001	5	0	12	\$ 6,083	\$ 6,083	\$ -		\$ 10,000	4	Desktop Review	Poor	3.0	3.0	9.0	
AIR-140	Mach/Equip	Software	Air Transportation	4622 Airport Rd				ALFA SOFTWARE	2011	10	8	2	\$ 21,500	\$ 4,300	\$ 17,200		\$ 20,000	2	Desktop Review	Good	2.0	3.0	6.0	
AIR-141	Mach/Equip	Software	Air Transportation	4623 Airport Rd				AIRMAN (Wildlife and Misc Modules)	2011	10	8	2	\$ 7,500	\$ 1,500	\$ 6,000		\$ 20,000	2	Desktop Review	Good	2.0	3.0	6.0	
AIR-142	Mach/Equip	Software	Air Transportation	4624 Airport Rd				Precise Parklink Entry Ticket system	2012	10	9	1	\$ 6,351	\$ 635	\$ 5,715		\$ 20,000	1	Desktop Review	Good	2.0	3.0	6.0	
AIR-143	Mach/Equip	Office	Air Transportation	4625 Airport Rd				Workbenches (4)	2012	10	9	1	\$ 8,408	\$ 841	\$ 7,567		\$ 1,000	1	Desktop Review	Good	2.0	3.0	6.0	