

City of Timmins
2014 Asset Management Plan
Watermains

Basic Asset/Component Information																Financial Accounting Values			Condition / Performance and Risk Assessment Information								Critical Maintenance Activities / Immediate Replacement	Infrastructure Assets Required to Impaired System Performance	
ID #	Category	Sub-Category	Department	Street	From	To	Diameter (mm)	Type	Length (m)	Year of Acquisition	PSAB U Life	PSAB Remaining UL	Useful Life	Remaining Useful Life	Age	Historical Cost December 31, 2012	Accumulated Amortization December 31, 2012	Net Book Value December 31, 2012	Replacement Cost	Condition Rating	Method of Last Condition Assessment	Asset Conditions / Deficiencies	Probability of Failure	Consequence of Failure	Risk / Criticality				
																22,694,435.75	8,894,423	13,800,013	102,544,000										
56	Infrastructure	Water Mains	Water Mains	ACRES CRES	PARK AVE	CLOVER CRES	150	DUCTILE IRON	215.0	1997	50	34	75	59	16	\$ 37,185	\$ 11,899	\$ 25,286	\$ 80,000	2	Desk top review	Good	2.0	1.3	2.6				
0396	Infrastructure	Water Mains	Water Mains	AIRPORT RD	MCCHESNEY RD	LONERGAN BLVD	400	DUCTILE IRON	722.4	1977	50	14	75	39	36	\$ 62,373	\$ 44,908	\$ 17,464	\$ 510,000	3	Desk top review	Fair	2.0	3.5	7.0				
0395	Infrastructure	Water Mains	Water Mains	AIRPORT RD	LAMMINEN AVE	MCCHESNEY RD	200	DUCTILE IRON	143.3	1972	50	9	75	34	41	\$ 8,007	\$ 6,565	\$ 1,441	\$ 60,000	3	Desk top review	Fair	2.0	1.6	3.2				
0640	Infrastructure	Water Mains	Water Mains	ALGONQUIN BLVD	INTERSECTION OF CAMERON	INTERSECTION OF CAMERON	150	PVC	35.0	2005	50	42	75	67	8	\$ 8,413	\$ 1,346	\$ 7,067	\$ 10,000	1	Desk top review	Very Good	1.0	1.3	1.3				
0645	Infrastructure	Water Mains	Water Mains	ALGONQUIN BLVD	PINE ST	BRUNETTE RD	250	DUCTILE IRON	435.9	1940	50	0	75	2	73	\$ 5,573	\$ 5,573	\$ -	\$ 200,000	5	Desk top review	Poor	4.0	2.0	8.0				
0648	Infrastructure	Water Mains	Water Mains	ALGONQUIN BLVD	(FORMER) DORANS BREWERY	BON AIR MOTEL	200	DUCTILE IRON	73.2	1940	50	0	75	2	73	\$ 873	\$ 873	\$ -	\$ 30,000	5	Desk top review	Poor	4.0	1.6	6.4				
0649	Infrastructure	Water Mains	Water Mains	ALGONQUIN BLVD	BRUNETTE RD	HWY 655	200	DUCTILE IRON	259.1	1940	50	0	75	2	73	\$ 3,092	\$ 3,092	\$ -	\$ 100,000	5	Desk top review	Poor	4.0	1.6	3.2				
0644	Infrastructure	Water Mains	Water Mains	ALGONQUIN BLVD	CEDAR ST	PINE ST	200	DUCTILE IRON	91.4	1940	50	0	75	2	73	\$ 1,091	\$ 1,091	\$ -	\$ 40,000	5	Desk top review	Poor	4.0	1.6	6.4				
0642	Infrastructure	Water Mains	Water Mains	ALGONQUIN BLVD	ELM ST	BIRCH ST	200	DUCTILE IRON	106.7	1940	50	0	75	2	73	\$ 1,273	\$ 1,273	\$ -	\$ 40,000	5	Desk top review	Poor	4.0	1.6	6.4				
0643	Infrastructure	Water Mains	Water Mains	ALGONQUIN BLVD	BIRCH ST	CEDAR ST	150	DUCTILE IRON	164.6	1940	50	0	75	2	73	\$ 1,684	\$ 1,684	\$ -	\$ 60,000	5	Desk top review	Poor	4.0	1.3	5.2				
0641	Infrastructure	Water Mains	Water Mains	ALGONQUIN BLVD	CAMERON ST	MOUNTJOY ST	150	DUCTILE IRON	499.9	1940	50	0	75	2	73	\$ 5,113	\$ 5,113	\$ -	\$ 170,000	5	Desk top review	Poor	4.0	1.3	5.2				
0639	Infrastructure	Water Mains	Water Mains	ALGONQUIN BLVD	MATTAGAMI RIVER BRIDGE	CAMERON ST	150	DUCTILE IRON	908.3	1940	50	0	75	2	73	\$ 9,291	\$ 9,291	\$ -	\$ 320,000	5	Desk top review	Poor	4.0	1.3	5.2				
0646	Infrastructure	Water Mains	Water Mains	ALGONQUIN BLVD	ONR OVERPASS	(FORMER) DORANS BREWERY	150	DUCTILE IRON	48.8	1940	50	0	75	2	73	\$ 499	\$ 499	\$ -	\$ 20,000	5	Desk top review	Poor	4.0	1.3	5.2				
0647	Infrastructure	Water Mains	Water Mains	ALGONQUIN BLVD	ONR OVERPASS	BON AIR MOTEL	150	DUCTILE IRON	106.7	1940	50	0	75	2	73	\$ 1,091	\$ 1,091	\$ -	\$ 40,000	5	Desk top review	Poor	4.0	1.3	5.2				
0167	Infrastructure	Water Mains	Water Mains	ALLAN ST	ALMA LANE	DUNN AVE	150	DUCTILE IRON	307.8	1935	50	0	75	0	78	\$ 2,889	\$ 2,889	\$ -	\$ 110,000	5	Desk top review	Poor	4.0	1.3	5.2				
0314	Infrastructure	Water Mains	Water Mains	ANKERITE RD	WEST ENT OF GOLDMINE RD	EAST ENT OF GOLDMINE RD	100	DUCTILE IRON	326.1	1985	50	22	75	47	28	\$ 35,285	\$ 19,760	\$ 15,525	\$ 100,000	2	Desk top review	Good	2.0	1.1	2.2				
0470	Infrastructure	Water Mains	Water Mains	ANN AVE	GILLIES ST	FOGG ST	200	DUCTILE IRON	100.6	1940	50	0	75	2	73	\$ 1,200	\$ 1,200	\$ -	\$ 40,000	5	Desk top review	Poor	4.0	1.6	6.4				
0469	Infrastructure	Water Mains	Water Mains	ANN AVE	CAMERON ST	AVENUE RD	150	DUCTILE IRON	115.8	1940	50	0	75	2	73	\$ 1,185	\$ 1,185	\$ -	\$ 40,000	5	Desk top review	Poor	4.0	1.3	5.2				
0501	Infrastructure	Water Mains	Water Mains	ARCHIE DILLON SPORTSPLEX	THERRAULT BLVD	MELROSE ST	200	DUCTILE IRON	201.2	1971	50	8	75	33	42	\$ 10,438	\$ 8,768	\$ 1,670	\$ 80,000	3	Desk top review	Fair	2.0	1.6	3.2				
0316	Infrastructure	Water Mains	Water Mains	ARGENTO BLVD	JV BONHOMME BLVD	NORTHEAST	150	PVC	245.0	2010	50	47	75	72	3	\$ 57,850	\$ 3,471	\$ 54,379	\$ 90,000	1	Desk top review	Very Good	1.0	1.3	1.3				
0316	Infrastructure	Water Mains	Water Mains	AUNOR RD	MACDONALD LAKE PLANT	KENVILLE DR	150	DUCTILE IRON	2,097.0	1985	50	22	75	47	28	\$ 247,506	\$ 138,603	\$ 108,903	\$ 730,000	2	Desk top review	Good	2.0	1.3	2.6				
0315	Infrastructure	Water Mains	Water Mains	AUNOR RD	MACDONALD LAKE PLANT	NUCKET CR	100	DUCTILE IRON	688.8	1985	50	22	75	47	28	\$ 74,528	\$ 41,735	\$ 32,792	\$ 210,000	2	Desk top review	Good	2.0	1.1	2.2				
0296	Infrastructure	Water Mains	Water Mains	AURA LAKE ST	FOURTH AVE	DWYER AVE	150	PVC	165.0	2003	50	40	75	65	10	\$ 35,345	\$ 7,069	\$ 28,276	\$ 60,000	1	Desk top review	Very Good	1.0	1.3	1.3				
0295	Infrastructure	Water Mains	Water Mains	AURA LAKE ST	HYDRO (ROW)	FOURTH AVE	300	DUCTILE IRON	109.7	1935	50	0	75	0	78	\$ 1,373	\$ 1,373	\$ -	\$ 50,000	5	Desk top review	Very Poor	4.0	2.4	9.6				
0297	Infrastructure	Water Mains	Water Mains	BALASAY COURT	FATHER COSTELLO DR	LIONS CREST LANE	100	DUCTILE IRON	67.1	1935	50	0	75	0	78	\$ 577	\$ 577	\$ -	\$ 20,000	5	Desk top review	Poor	4.0	1.1	4.4		Replace within 3 to 5 years		
0463	Infrastructure	Water Mains	Water Mains	AUXILIA RD	MCCHESNEY RD	TIMMINS HIGH & VOC SCHOOL	200	DUCTILE IRON	603.5	1980	50	17	75	42	33	\$ 59,658	\$ 39,375	\$ 20,284	\$ 240,000	3	Desk top review	Fair	2.0	1.6	3.2				
0467	Infrastructure	Water Mains	Water Mains	AVENUE RD	ALGONQUIN BLVD	ANN AVE	150	DUCTILE IRON	271.3	1940	50	0	75	2	73	\$ 2,775	\$ 2,775	\$ -	\$ 90,000	5	Desk top review	Poor	4.0	1.3	5.2				
0547	Infrastructure	Water Mains	Water Mains	BALSAM ST	EIGHTH AVE	NINTH AVE	200	PVC	237.7	1940	50	0	75	2	73	\$ 2,837	\$ 2,837	\$ -	\$ 100,000	5	Desk top review	Poor	4.0	1.6	6.4				
0544	Infrastructure	Water Mains	Water Mains	BALSAM ST	SECOND AVE	THIRD AVE	250	DUCTILE IRON	109.7	1940	50	0	75	2	73	\$ 1,403	\$ 1,403	\$ -	\$ 50,000	5	Desk top review	Poor	4.0	2.0	8.0				
0548	Infrastructure	Water Mains	Water Mains	BALSAM ST	NINTH AVE	NORTH TO END	200	DUCTILE IRON	140.2	1940	50	0	75	2	73	\$ 1,673	\$ 1,673	\$ -	\$ 60,000	5	Desk top review	Poor	4.0	1.6	6.4				
0545	Infrastructure	Water Mains	Water Mains	BALSAM ST	THIRD AVE	FOURTH AVE	200	DUCTILE IRON	234.7	1940	50	0	75	2	73	\$ 2,801	\$ 2,801	\$ -	\$ 90,000	5	Desk top review	Poor	4.0	1.6	6.4				
0546	Infrastructure	Water Mains	Water Mains	BALSAM ST	FIFTH AVE	EIGHTH AVE	150	DUCTILE IRON	378.0	1940	50	0	75	2	73	\$ 3,866	\$ 3,866	\$ -	\$ 130,000	5	Desk top review	Poor	4.0	1.3	5.2				
0549	Infrastructure	Water Mains	Water Mains	BALSAM ST	JUBILEE AVE	BROUSSEAU AVE	150	DUCTILE IRON	121.9	1940	50	0	75	2	73	\$ 1,247	\$ 1,247	\$ -	\$ 40,000	5	Desk top review	Poor	4.0	1.3	5.2				
0543	Infrastructure	Water Mains	Water Mains	BALSAM ST	MONETA AVE	SECOND AVE	150	DUCTILE IRON	634.0	1940	50	0	75	2	73	\$ 6,485	\$ 6,485	\$ -	\$ 220,000	5	Desk top review	Poor	4.0	1.3	5.2				
0542	Infrastructure	Water Mains	Water Mains	BALSAM ST	STIRLING AVE	MONETA AVE	150	DUCTILE IRON	231.6	1940	50	0	75	2	73	\$ 2,369	\$ 2,369	\$ -	\$ 80,000	5	Desk top review	Poor	4						

City of Timmins
2014 Asset Management Plan
Watermains

Basic Asset/Component Information																Financial Accounting Values			Condition / Performance and Risk Assessment Information									Infrastructure Assets Required to Improved System Performance
ID #	Category	Sub-Category	Department	Street	From	To	Diameter (mm)	Type	Length (m)	Year of Acquisition	PSAB U Life	PSAB Remaining UL	Useful Life	Remaining Useful Life	Age	Historical Cost December 31, 2012	Accumulated Amortization December 31, 2012	Net Book Value December 31, 2012	Replacement Cost	Condition Rating	Method of Last Condition Assessment	Asset Conditions / Deficiencies	Probability of Failure	Consequence of Failure	Risk / Criticality	Critical Maintenance Activities / Immediate Replacement		
0036	Infrastructure	Water Mains	Water Mains	CHENIER AVE	MAURICE ST	CHANTAL CR	150	DUCTILE IRON	80.0	1975	50	12	75	37	38	\$ 5,330	\$ 4,051	\$ 1,279	\$ 30,000	3	Desk top review	Fair	2.0	1.3	2.6			
0567	Infrastructure	Water Mains	Water Mains	CHERRY ST	EMPIRE AVE	CHERRY ST	150	DUCTILE IRON	167.6	1940	50	0	75	2	73	\$ 1,715	\$ 1,715	\$ -	\$ 60,000	5	Desk top review	Poor	4.0	1.3	5.2			
0568	Infrastructure	Water Mains	Water Mains	CHERRY ST	TOKE ST	NORTH TO END	150	DUCTILE IRON	167.6	1940	50	0	75	2	73	\$ 1,715	\$ 1,715	\$ -	\$ 60,000	5	Desk top review	Poor	4.0	1.3	5.2			
0043	Infrastructure	Water Mains	Water Mains	CHESTNUT LANE	CLIFFORD ST	JOSEPH ST	150	DUCTILE IRON	219.5	1980	50	17	75	42	33	\$ 18,595	\$ 12,273	\$ 6,322	\$ 80,000	3	Desk top review	Fair	2.0	1.3	2.6			
0039	Infrastructure	Water Mains	Water Mains	CHRISTINE ST	CHENIER ST	CAMILLE ST	150	DUCTILE IRON	274.3	1975	50	12	75	37	38	\$ 18,278	\$ 13,891	\$ 4,387	\$ 100,000	3	Desk top review	Fair	2.0	1.3	2.6			
0423	Infrastructure	Water Mains	Water Mains	CHURCHILL ST	WESTMOUNT BLVD	VICTORIA AVE	150	PVC	210.3	1960	50	0	75	22	53	\$ 5,472	\$ 5,472	\$ -	\$ 70,000	4	Desk top review	Fair	3.0	1.3	3.9			
0424	Infrastructure	Water Mains	Water Mains	CHURCHILL ST	END OF CUL DE SAC	WESTMOUNT BLVD	150	DUCTILE IRON	176.8	1960	50	0	75	22	53	\$ 4,599	\$ 4,599	\$ -	\$ 60,000	4	Desk top review	Fair	3.0	1.3	3.9			
0310	Infrastructure	Water Mains	Water Mains	CLAMPOST TRAIL	BRUNDY AVE	SOUTH TO END	200	DUCTILE IRON	189.0	1980	50	17	75	42	33	\$ 18,681	\$ 12,329	\$ 6,352	\$ 80,000	3	Desk top review	Fair	2.0	1.6	3.2			
0182	Infrastructure	Water Mains	Water Mains	CLEMENT ST	FERGUSON RD	MICHENER BLVD	200	DUCTILE IRON	225.6	1975	50	12	75	37	38	\$ 17,533	\$ 13,325	\$ 4,208	\$ 90,000	3	Desk top review	Fair	2.0	1.6	3.2			
0041	Infrastructure	Water Mains	Water Mains	CLIFFORD ST	RIVERSIDE DR	POWER AVE	150	DUCTILE IRON	341.4	1976	50	13	75	38	37	\$ 22,107	\$ 16,359	\$ 5,748	\$ 120,000	3	Desk top review	Fair	2.0	1.3	2.6			
0605	Infrastructure	Water Mains	Water Mains	CLOUTIER ST	ALGONQUIN BLVD	WILSON AVE	150	DUCTILE IRON	70.1	1950	50	0	75	12	63	\$ 1,247	\$ 1,247	\$ -	\$ 20,000	4	Desk top review	Fair	3.0	1.3	3.9			
0606	Infrastructure	Water Mains	Water Mains	CLOUTIER ST	BELANGER AVE	BANNERMAN AVE	150	DUCTILE IRON	146.3	1950	50	0	75	12	63	\$ 2,603	\$ 2,603	\$ -	\$ 50,000	4	Desk top review	Fair	3.0	1.3	3.9			
0057	Infrastructure	Water Mains	Water Mains	CLOVER CRES	ACRES CRES	WHEATFIELD RD	150	DUCTILE IRON	155.4	1997	50	34	75	59	16	\$ 26,885	\$ 8,603	\$ 18,282	\$ 50,000	2	Desk top review	Good	2.0	1.3	2.6			
0597	Infrastructure	Water Mains	Water Mains	CODY AVE	WILCOX ST	ELM ST	150	PVC	201.2	1950	50	0	75	12	63	\$ 3,579	\$ 3,579	\$ -	\$ 70,000	4	Desk top review	Fair	3.0	1.3	3.9			
0596	Infrastructure	Water Mains	Water Mains	CODY AVE	DELMONTE LANE	WILCOX ST	150	DUCTILE IRON	185.9	1950	50	0	75	12	63	\$ 3,307	\$ 3,307	\$ -	\$ 70,000	4	Desk top review	Fair	3.0	1.3	3.9			
0405	Infrastructure	Water Mains	Water Mains	COLLEGE ST	AIRPORT RD	VICTORIA AVE	250	DUCTILE IRON	435.9	1971	50	8	75	33	42	\$ 24,230	\$ 20,353	\$ 3,877	\$ 200,000	3	Desk top review	Fair	2.0	2.0	4.0			
0406	Infrastructure	Water Mains	Water Mains	COLLEGE ST	VICTORIA AVE	RAY CANIE BLVD	200	DUCTILE IRON	365.8	1986	50	23	75	48	27	\$ 53,502	\$ 28,891	\$ 24,611	\$ 150,000	2	Desk top review	Good	2.0	1.6	3.2			
0415	Infrastructure	Water Mains	Water Mains	COLLEGE ST (ROW)	JUBILEE AVE	VICTORIA AVE	150	DUCTILE IRON	435.9	1960	50	0	75	22	53	\$ 11,340	\$ 11,340	\$ -	\$ 150,000	4	Desk top review	Fair	3.0	1.3	3.9			
0261	Infrastructure	Water Mains	Water Mains	COLLINS COURT	KENNETH CRES	SOUTH TO END OF COLLINS	150	DUCTILE IRON	82.3	1990	50	27	75	52	23	\$ 13,497	\$ 6,209	\$ 7,288	\$ 30,000	2	Desk top review	Good	2.0	1.3	2.6			
0592	Infrastructure	Water Mains	Water Mains	COLUMBUS AVE	CAMERON ST	MOUNTJOY ST	150	DUCTILE IRON	502.9	1940	50	0	75	2	73	\$ 5,144	\$ 5,144	\$ -	\$ 180,000	5	Desk top review	Poor	4.0	1.3	5.2			
	Infrastructure	Water Mains	Water Mains	COMMERCIAL AVE	CLOUTIER ST	CAMERON ST	250	PVC	154.0	2006	50	43	75	68	7	\$ 49,378	\$ 6,913	\$ 42,465	\$ 70,000	1	Desk top review	Good	1.0	2.0	2.0	Split watermain into 2 sections & add new asset ID# 0582B. This section should be assessed for possible replacement within 1 to 3 years.		
0582	Infrastructure	Water Mains	Water Mains	COMMERCIAL AVE	MATTAGAMI BLVD	MOUNTJOY ST	500	DUCTILE IRON	800.0	1940	50	0	75	2	73	\$ 10,228	\$ 10,228	\$ -	\$ 880,000	5	Desk top review	Very Poor	4.0	5.0	20.0	Replace within 1 to 2 years to ensure security of supply. Watermain has failed numerous times and is beyond repair.		
0582B	Infrastructure	Water Mains	Water Mains	COMMERCIAL AVE	TIMMINS WATER PLANT	MATTAGAMI BLVD	500	DUCTILE IRON	480.2	1940	50	0	75	2	73	\$ 6,140	\$ 6,140	\$ -	\$ 530,000	5	Desk top review	Very Poor	4.0	5.0	20.0			
0581	Infrastructure	Water Mains	Water Mains	COMMERCIAL AVE	MATTAGAMI BLVD	CLOUTIER ST	250	DUCTILE IRON	780.0	1940	50	0	75	2	73	\$ 9,973	\$ 9,973	\$ -	\$ 350,000	5	Desk top review	Poor	4.0	2.0	8.0			
0257	Infrastructure	Water Mains	Water Mains	CONLEY ST	GAUTHIER ST	LAMARCHE ST	150	DUCTILE IRON	115.8	1935	50	0	75	0	78	\$ 1,087	\$ 1,087	\$ -	\$ 40,000	5	Desk top review	Poor	4.0	1.3	5.2			
0258	Infrastructure	Water Mains	Water Mains	CONLEY ST	HWY 101	LAMARCHE ST	150	DUCTILE IRON	88.4	1935	50	0	75	0	78	\$ 829	\$ 829	\$ -	\$ 30,000	5	Desk top review	Poor	4.0	1.3	5.2			
0242	Infrastructure	Water Mains	Water Mains	CONLEY ST	EARL ST	DUKE ST	150	DUCTILE IRON	99.0	1985	50	22	75	47	28	\$ 11,685	\$ 6,543	\$ 5,141	\$ 30,000	2	Desk top review	Good	2.0	1.3	2.6			
0432	Infrastructure	Water Mains	Water Mains	CONRAD COURT	LAVIGNE BLVD	EAST TO END	150	DUCTILE IRON	225.6	2000	50	37	75	62	13	\$ 43,839	\$ 11,398	\$ 32,441	\$ 80,000	1	Desk top review	Very Good	1.0	1.3	1.3			
0313	Infrastructure	Water Mains	Water Mains	COOK RD	GOLDMINE RD	NORTH TO END	100	DUCTILE IRON	112.8	1985	50	22	75	47	28	\$ 12,201	\$ 6,833	\$ 5,369	\$ 30,000	2	Desk top review	Good	2.0	1.1	2.2			
0245	Infrastructure	Water Mains	Water Mains	COOT LANE	KING ST	DIXON ST	150	DUCTILE IRON	88.4	1935	50	0	75	0	78	\$ 829	\$ 829	\$ -	\$ 30,000	5	Desk top review	Poor	4.0	1.3	5.2			
0599	Infrastructure	Water Mains	Water Mains	CORONATION AVE	WILCOX ST	MOUNTJOY ST	150	DUCTILE IRON	118.9	1950	50	0	75	12	63	\$ 2,115	\$ 2,115	\$ -	\$ 40,000	4	Desk top review	Fair	3.0	1.3	3.9			
0213	Infrastructure	Water Mains	Water Mains	CORPORATION ST	FLORENCE ST	HWY 101	150	DUCTILE IRON	411.5	1935	50	0	75	0	78	\$ 3,861	\$ 3,861	\$ -	\$ 140,000	5	Desk top review	Poor	4.0	1.3	5.2			
0377	Infrastructure	Water Mains	Water Mains	COUTURE AVE	SUZANNE ST	DENISE ST	150	DUCTILE IRON	295.7	1972	50	9	75	34	41	\$ 14,164	\$ 11,614	\$ 2,549	\$ 100,000	3	Desk top review	Fair	2.0	1.3	2.6			
0063	Infrastructure	Water Mains	Water Mains	CRAIG ST	NORMAN ST	RIVERSIDE DR	150	DUCTILE IRON	530.4	1968	50	5	75	30	45	\$ 18,798	\$ 16,918	\$ 1,880	\$ 190,000	3	Desk top review	Fair	2.0	1.3	2.6			
	Infrastructure	Water Mains	Water Mains	CRAWFORD ST	GOLDEN AVE	HELLEN AVE	300	DUCTILE IRON	430.0	1980	50	17	75	42	33	\$ 48,579	\$ 32,062	\$ 16,517	\$ 220,000									

City of Timmins
2014 Asset Management Plan
Watermains

Basic Asset/Component Information																Financial Accounting Values			Condition / Performance and Risk Assessment Information								Critical Maintenance Activities / Immediate Replacement	Infrastructure Assets Required to Impaired System Performance
ID #	Category	Sub-Category	Department	Street	From	To	Diameter (mm)	Type	Length (m)	Year of Acquisition	PSAB U Life	PSAB Remaining UL	Useful Life	Remaining Useful Life	Age	Historical Cost December 31, 2012	Accumulated Amortization December 31, 2012	Net Book Value December 31, 2012	Replacement Cost	Condition Rating	Method of Last Condition Assessment	Asset Conditions / Deficiencies	Probability of Failure	Consequence of Failure	Risk / Criticality			
0425	Infrastructure	Water Mains	Water Mains	EYRE BLVD	JUBILEE AVE	VICTORIA AVE	150	DUCTILE IRON	435.9	1960	50	0	75	22	53	\$ 11,340	\$ 11,340	\$ -	\$ 150,000	4	Desk top review	Fair	3.0	1.3	3.9			
0007	Infrastructure	Water Mains	Water Mains	FABIAN ST	SOUTH TO RIVERSIDE DR ROW		200	DUCTILE IRON	27.4	1958	50	5	75	30	45	\$ 972	\$ 975	\$ 97	\$ 10,000	3	Desk top review	Fair	2.0	1.3	2.6			
0241	Infrastructure	Water Mains	Water Mains	FALCON ST	ONR (ROW)	HWY 101	200	DUCTILE IRON	304.8	1935	50	0	75	0	78	\$ 3,337	\$ 3,337	\$ -	\$ 120,000	5	Desk top review	Fair	4.0	1.6	6.4			
0240	Infrastructure	Water Mains	Water Mains	FALCON ST	DUKE ST	EARL ST	150	DUCTILE IRON	94.5	1935	50	0	75	0	78	\$ 887	\$ 887	\$ -	\$ 30,000	5	Desk top review	Fair	4.0	1.3	5.2			
0239	Infrastructure	Water Mains	Water Mains	FALCON ST	GERVAIS ST	QUEEN ST	150	DUCTILE IRON	70.1	1935	50	0	75	0	78	\$ 658	\$ 658	\$ -	\$ 20,000	5	Desk top review	Fair	4.0	1.3	5.2			
0265	Infrastructure	Water Mains	Water Mains	FATHER COSTELLO DR	GRANT ST	AURA LAKE ST	200	PVC	182.9	2005	50	42	75	67	8	\$ 51,287	\$ 8,206	\$ 43,081	\$ 70,000	1	Desk top review	Good	1.0	1.6	1.6			
0264	Infrastructure	Water Mains	Water Mains	FATHER COSTELLO DR	VIPOND RD	GRANT ST	300	DUCTILE IRON	210.3	1994	50	31	75	56	19	\$ 45,212	\$ 17,181	\$ 28,032	\$ 110,000	2	Desk top review	Good	2.0	2.4	4.8			
0263	Infrastructure	Water Mains	Water Mains	FATHER COSTELLO DR	HOLLINGER LANE		250	DUCTILE IRON	204.2	1935	50	0	75	0	78	\$ 2,395	\$ 2,395	\$ -	\$ 90,000	5	Desk top review	Fair	4.0	2.0	8.0			
0266	Infrastructure	Water Mains	Water Mains	FATHER COSTELLO DR	AURA LAKE ST	BOUNDARY LANE	200	DUCTILE IRON	131.1	1935	50	0	75	0	78	\$ 1,435	\$ 1,435	\$ -	\$ 50,000	5	Desk top review	Fair	4.0	1.6	6.4			
0267	Infrastructure	Water Mains	Water Mains	FATHER COSTELLO DR	BOUNDARY LANE	CARIUM RD	200	DUCTILE IRON	548.6	1935	50	0	75	0	78	\$ 6,006	\$ 6,006	\$ -	\$ 220,000	5	Desk top review	Fair	4.0	1.6	6.4			
0391	Infrastructure	Water Mains	Water Mains	FAY CRES	EMILIE ST	EASTERLY	150	DUCTILE IRON	115.8	1971	50	8	75	33	42	\$ 5,151	\$ 4,327	\$ 824	\$ 40,000	3	Desk top review	Fair	2.0	1.3	2.6			
	Infrastructure	Water Mains	Water Mains	FERGUSON RD	CLEMENT ST	HWY 101	300	DUCTILE IRON	120.0	1999	50	36	75	61	14	\$ 28,870	\$ 8,084	\$ 20,786	\$ 60,000	1	Desk top review	Good	1.0	2.4	2.4			
0191	Infrastructure	Water Mains	Water Mains	FERGUSON RD	CLEMENT ST	HWY 101	300	DUCTILE IRON	400.0	2000	50	37	75	62	13	\$ 103,660	\$ 26,952	\$ 76,708	\$ 200,000	1	Desk top review	Good	1.0	2.4	2.4			
0190	Infrastructure	Water Mains	Water Mains	FERGUSON RD	SPILLENAR ST	CLEMENT ST	150	DUCTILE IRON	253.0	1935	50	0	75	0	78	\$ 2,374	\$ 2,374	\$ -	\$ 90,000	5	Desk top review	Fair	4.0	1.3	5.2			
0104	Infrastructure	Water Mains	Water Mains	FERN AVE	MOORE ST	MAIN ST	300	PVC	167.6	1935	50	0	75	0	78	\$ 2,097	\$ 2,097	\$ -	\$ 60,000	5	Desk top review	Poor	4.0	2.4	9.6	Replace within 3 to 5 years		
0103	Infrastructure	Water Mains	Water Mains	FERN AVE	LEGION DR	MOORE ST	200	DUCTILE IRON	156.0	2002	50	39	75	64	11	\$ 37,594	\$ 8,271	\$ 29,323	\$ 60,000	1	Desk top review	Good	1.0	1.6	1.6			
0106	Infrastructure	Water Mains	Water Mains	FERN AVE	MAIN ST	CRAWFORD ST	150	DUCTILE IRON	128.0	1935	50	0	75	0	78	\$ 1,201	\$ 1,201	\$ -	\$ 40,000	5	Desk top review	Fair	4.0	1.3	5.2			
0105	Infrastructure	Water Mains	Water Mains	FERN AVE	MAIN ST	CRAWFORD ST	100	DUCTILE IRON	128.0	1935	50	0	75	0	78	\$ 1,101	\$ 1,101	\$ -	\$ 40,000	5	Desk top review	Poor	4.0	1.1	4.4			
0520	Infrastructure	Water Mains	Water Mains	FIFTH AVE	BIRCH ST	HEMLOCK ST	200	DUCTILE IRON	475.5	1940	50	0	75	2	73	\$ 5,674	\$ 5,674	\$ -	\$ 190,000	5	Desk top review	Poor	4.0	1.6	6.4			
0521	Infrastructure	Water Mains	Water Mains	FIFTH AVE	MCINTOSH ST		150	DUCTILE IRON	36.6	1940	50	0	75	2	73	\$ 374	\$ 374	\$ -	\$ 10,000	5	Desk top review	Poor	4.0	1.3	5.2			
0621	Infrastructure	Water Mains	Water Mains	FIRST AVE	FIRST AVE	BRUNETTE RD	150	DUCTILE IRON	438.9	1940	50	0	75	2	73	\$ 4,489	\$ 4,489	\$ -	\$ 150,000	5	Desk top review	Poor	4.0	1.3	5.2			
0620	Infrastructure	Water Mains	Water Mains	FIRST AVE (EASEMENT)	ELM ST	BIRCH ST	150	DUCTILE IRON	158.5	1940	50	0	75	2	73	\$ 1,621	\$ 1,621	\$ -	\$ 60,000	5	Desk top review	Poor	4.0	1.3	5.2			
0619	Infrastructure	Water Mains	Water Mains	FIRST AVE (EASEMENT)	PINE ST	SPRUCE ST	150	DUCTILE IRON	79.2	1940	50	0	75	2	73	\$ 811	\$ 811	\$ -	\$ 30,000	5	Desk top review	Poor	4.0	1.3	5.2			
0485	Infrastructure	Water Mains	Water Mains	FLORAL AVE	REA ST	MACLEAN DR	150	DUCTILE IRON	359.7	1940	50	0	75	2	73	\$ 3,679	\$ 3,679	\$ -	\$ 130,000	5	Desk top review	Poor	4.0	1.3	5.2			
0210	Infrastructure	Water Mains	Water Mains	FLORENCE ST	BRISTOL RD	HWY 101	150	DUCTILE IRON	274.3	1935	50	0	75	0	78	\$ 2,574	\$ 2,574	\$ -	\$ 100,000	5	Desk top review	Poor	4.0	1.3	5.2			
0195	Infrastructure	Water Mains	Water Mains	FLORENCE ST	REMEMBRANCE ST		150	DUCTILE IRON	290.4	1935	50	0	75	0	78	\$ 2,631	\$ 2,631	\$ -	\$ 100,000	5	Desk top review	Poor	4.0	1.3	5.2			
0466	Infrastructure	Water Mains	Water Mains	FOREST PLACE	FOGG ST	ANN AVE	150	DUCTILE IRON	341.4	1940	50	0	75	2	73	\$ 3,492	\$ 3,492	\$ -	\$ 120,000	5	Desk top review	Poor	4.0	1.3	5.2			
0059	Infrastructure	Water Mains	Water Mains	FOREST PLACE	LYNWOOD DR	WEST TO END	150	DUCTILE IRON	48.8	1981	50	18	75	43	32	\$ 4,718	\$ 3,020	\$ 1,698	\$ 20,000	3	Desk top review	Fair	2.0	1.3	2.6			
0279	Infrastructure	Water Mains	Water Mains	FOURTH AVE	AURA LAKE ST	BOUNDARY LANE	200	DUCTILE IRON	137.2	1935	50	0	75	0	78	\$ 1,502	\$ 1,502	\$ -	\$ 50,000	5	Desk top review	Poor	4.0	1.6	6.4			
0280	Infrastructure	Water Mains	Water Mains	FOURTH AVE	BATTACHIO ST	AURA LAKE ST	150	DUCTILE IRON	326.1	1935	50	0	75	0	78	\$ 3,060	\$ 3,060	\$ -	\$ 110,000	5	Desk top review	Poor	4.0	1.3	5.2			
0281	Infrastructure	Water Mains	Water Mains	FOURTH AVE	VIPOND RD	BATTACHIO ST	150	DUCTILE IRON	76.2	1935	50	0	75	0	78	\$ 715	\$ 715	\$ -	\$ 30,000	5	Desk top review	Poor	4.0	1.3	5.2			
0278	Infrastructure	Water Mains	Water Mains	FOURTH AVE	BOUNDARY LANE	VETERANS ST	150	DUCTILE IRON	158.5	1970	50	7	75	32	43	\$ 6,485	\$ 5,577	\$ 908	\$ 60,000	3	Desk top review	Fair	2.0	1.3	2.6			
0277	Infrastructure	Water Mains	Water Mains	FOURTH AVE	VETERANS ST	PONDEROSA ST	150	DUCTILE IRON	167.6	1970	50	7	75	32	43	\$ 6,355	\$ 5,899	\$ 456	\$ 60,000	3	Desk top review	Fair	2.0	1.3	2.6			
0149	Infrastructure	Water Mains	Water Mains	FRONT ST	ESSA AVE	POWELL AVE	200	DUCTILE IRON	213.4	1935	50	0	75	0	78	\$ 2,336	\$ 2,336	\$ -	\$ 90,000	5	Desk top review	Poor	4.0	1.6	6.4			
0148	Infrastructure	Water Mains	Water Mains	FRONT ST	ESSA AVE	HWY 101	100	DUCTILE IRON	237.7	1935	50	0	75	0	78	\$ 2,045	\$ 2,045	\$ -	\$ 70,000	5	Desk top review	Poor	4.0	1.1	4.4			
0049	Infrastructure	Water Mains	Water Mains	FRONTENAC CRES	PARK AVE	CHAMPLAIN ST S	150	DUCTILE IRON	247.0	1972	50	9	75	34	41	\$ 11,833	\$ 9,											

City of Timmins
2014 Asset Management Plan
Watermains

Basic Asset/Component Information																Financial Accounting Values			Condition / Performance and Risk Assessment Information								Critical Maintenance Activities / Immediate Replacement	Infrastructure Assets Required to Improved System Performance
ID #	Category	Sub-Category	Department	Street	From	To	Diameter (mm)	Type	Length (m)	Year of Acquisition	PSAB U Life	PSAB Remaining UL	Useful Life	Remaining Useful Life	Age	Historical Cost December 31, 2012	Accumulated Amortization December 31, 2012	Net Book Value December 31, 2012	Replacement Cost	Condition Rating	Method of Last Condition Assessment	Asset Conditions / Deficiencies	Probability of Failure	Consequence of Failure	Risk / Criticality			
0014	Infrastructure	Water Mains	Water Mains	JAGUAR ROAD	RIVERSIDE DR	GOVERNMENT RD	300	DUCTILE IRON	435.9	1997	50	34	75	59	16	\$ 100,513	\$ 32,164	\$ 68,349	\$ 220,000	2	Desk top review	Good	2.0	2.4	4.8			
0365	Infrastructure	Water Mains	Water Mains	JAMES REID RD	MONETA AVE	SHANIA TWAIN CENTER	250	DUCTILE IRON	487.7	1999	50	36	75	61	14	\$ 109,994	\$ 30,798	\$ 79,195	\$ 220,000	1	Desk top review	Very Good	1.0	2.0	2.0			
0364	Infrastructure	Water Mains	Water Mains	JAMES REID RD	MONETA AVE	TIMMINS GOLD MINE TOUR	100	DUCTILE IRON	259.1	1990	50	27	75	52	23	\$ 38,949	\$ 17,916	\$ 21,032	\$ 80,000	2	Desk top review	Good	2.0	1.1	2.2			
0254	Infrastructure	Water Mains	Water Mains	JARVI ST	LAMARCHE ST	BOB'S LAKE DR	150	DUCTILE IRON	88.4	1935	50	0	75	0	78	\$ 829	\$ 829	\$ -	\$ 30,000	5	Desk top review	Poor	4.0	1.3	5.2			
0376	Infrastructure	Water Mains	Water Mains	JEAN ST	COUTURE AVE	MALETTE CRES	150	DUCTILE IRON	36.6	1972	50	9	75	34	41	\$ 1,752	\$ 1,437	\$ 315	\$ 10,000	3	Desk top review	Fair	2.0	1.3	2.6			
0325	Infrastructure	Water Mains	Water Mains	JEAN ST	COUTURE AVE	MALETTE CRES	150	DUCTILE IRON	36.6	1981	50	18	75	43	32	\$ 3,539	\$ 2,265	\$ 1,274	\$ 10,000	3	Desk top review	Fair	2.0	1.3	2.6			
0375	Infrastructure	Water Mains	Water Mains	JESSICA AVE	SAGE ST	LAKE SHORE RD	100	DUCTILE IRON	33.5	1985	50	22	75	47	28	\$ 3,627	\$ 2,031	\$ 1,596	\$ 10,000	2	Desk top review	Good	2.0	1.1	2.2			
0575	Infrastructure	Water Mains	Water Mains	JOHN AVE	TOKE ST	LAKE SHORE RD	150	DUCTILE IRON	85.3	1940	50	0	75	2	73	\$ 873	\$ 873	\$ -	\$ 30,000	5	Desk top review	Poor	4.0	1.3	5.2			
0044	Infrastructure	Water Mains	Water Mains	JOSEPH ST	RIVERSIDE DR	PARK AVE	300	DUCTILE IRON	548.6	1976	50	13	75	38	37	\$ 47,372	\$ 35,055	\$ 12,317	\$ 270,000	3	Desk top review	Fair	2.0	2.4	4.8			
0327B	Infrastructure	Water Mains	Water Mains	JUBILEE AVE	MACLEAN DR	BALSAM	150	PVC	362.2	2010	50	47	75	72	3	\$ 81,833	\$ 4,910	\$ 76,923	\$ 130,000	1	Desk top review	Very Good	1.0	1.3	1.3			
0327C	Infrastructure	Water Mains	Water Mains	JUBILEE AVE	MACLEAN DR	BALSAM	150	PVC	38.0	2010	50	47	75	72	3	\$ 10,732	\$ 644	\$ 10,088	\$ 10,000	1	Desk top review	Very Good	1.0	1.3	1.3			
0327E	Infrastructure	Water Mains	Water Mains	JUBILEE AVE	WATERLOO RD	WATERLOO RD	150	PVC	32.5	2011	50	48	75	73	2	\$ -	\$ -	\$ -	\$ 10,000	1	Desk top review	Very Good	1.0	1.3	1.3			
0327D	Infrastructure	Water Mains	Water Mains	JUBILEE AVE	REA ST	EYRE	150	PVC	232.3	2012	50	49	75	74	1	\$ 84,317	\$ 1,686	\$ 82,631	\$ 90,000	1	Desk top review	Very Good	1.0	1.3	1.3			
0327F	Infrastructure	Water Mains	Water Mains	JUBILEE AVE	MACLEAN DR	MACLEAN DR	150	PVC	205.5	2012	50	49	75	74	1	\$ 81,433	\$ 1,629	\$ 79,803	\$ 70,000	2	Desk top review	Very Good	1.0	1.3	1.3			
0327A	Infrastructure	Water Mains	Water Mains	JUBILEE AVE	THERIAULT BLVD	MACLEAN DR	150	DUCTILE IRON	240.1	1940	50	0	75	2	73	\$ 2,456	\$ 2,456	\$ -	\$ 80,000	5	Desk top review	Poor	4.0	1.3	5.2			
0095	Infrastructure	Water Mains	Water Mains	JULIE AVE	CRAWFORD ST	SONY ST	150	DUCTILE IRON	152.4	1973	50	10	75	35	40	\$ 7,967	\$ 6,373	\$ 1,593	\$ 50,000	3	Desk top review	Fair	2.0	1.3	2.6			
0574	Infrastructure	Water Mains	Water Mains	JURY LANE	JAMES AVE	ROCHESTER AVE	150	DUCTILE IRON	274.3	1940	50	0	75	2	73	\$ 2,806	\$ 2,806	\$ -	\$ 100,000	5	Desk top review	Poor	4.0	1.3	5.2			
0564	Infrastructure	Water Mains	Water Mains	KAY CRES	ROSS AVE	SOUTHERLY	150	DUCTILE IRON	103.6	1980	50	17	75	42	33	\$ 8,781	\$ 5,795	\$ 2,986	\$ 40,000	3	Desk top review	Fair	2.0	1.3	2.6			
0366	Infrastructure	Water Mains	Water Mains	KELLYANN DR	LONERGAN BLVD	RENEE PLACE	150	DUCTILE IRON	734.6	1990	50	27	75	52	23	\$ 120,470	\$ 55,416	\$ 65,054	\$ 260,000	2	Desk top review	Good	2.0	1.3	2.6			
0260	Infrastructure	Water Mains	Water Mains	KENNETH CRES	EARL ST	NORTH TO END	150	DUCTILE IRON	472.4	1990	50	27	75	52	23	\$ 77,481	\$ 35,641	\$ 41,840	\$ 170,000	2	Desk top review	Good	2.0	1.3	2.6			
0588	Infrastructure	Water Mains	Water Mains	KENT AVE	CAMERON ST	MOUNTJOY ST	150	DUCTILE IRON	502.9	1940	50	0	75	2	73	\$ 5,144	\$ 5,144	\$ -	\$ 180,000	5	Desk top review	Poor	4.0	1.3	5.2			
0320	Infrastructure	Water Mains	Water Mains	KENVILLE DR	DELNITE RD	SOUTH TO END	100	DUCTILE IRON	143.3	1985	50	22	75	47	28	\$ 15,499	\$ 8,679	\$ 6,820	\$ 40,000	2	Desk top review	Good	2.0	1.1	2.2			
0623	Infrastructure	Water Mains	Water Mains	KIMBERLY AVE	PINE ST	SPRUCE ST	150	DUCTILE IRON	82.3	1940	50	0	75	2	73	\$ 842	\$ 842	\$ -	\$ 30,000	5	Desk top review	Poor	4.0	1.3	5.2			
0252	Infrastructure	Water Mains	Water Mains	KING ST	HALLNOR RD	EAST TO NORFAB	300	PVC	195.1	1935	50	0	75	0	78	\$ 2,441	\$ 2,441	\$ -	\$ 100,000	5	Desk top review	Poor	4.0	2.4	9.6	Replace within 3 to 5 years		
0251	Infrastructure	Water Mains	Water Mains	KING ST	ONR (ROW)	HALLNOR RD	300	PVC	1,951.4	1935	50	0	75	0	78	\$ 19,411	\$ 19,411	\$ -	\$ 780,000	5	Desk top review	Poor	4.0	2.4	9.6	Replace within 3 to 5 years		
0348	Infrastructure	Water Mains	Water Mains	KIRBY AVE	ELM ST	COOT LANE	300	DUCTILE IRON	716.3	1996	50	33	75	58	17	\$ 161,791	\$ 55,009	\$ 106,782	\$ 360,000	2	Desk top review	Good	2.0	2.4	4.8			
0349	Infrastructure	Water Mains	Water Mains	KIRBY AVE	PINE ST	SPRUCE ST	150	DUCTILE IRON	82.3	1940	50	0	75	2	73	\$ 842	\$ 842	\$ -	\$ 30,000	5	Desk top review	Poor	4.0	1.3	5.2			
0350	Infrastructure	Water Mains	Water Mains	KIRBY AVE	RAILWAY ST	LAIDLAW ST	150	DUCTILE IRON	54.9	1940	50	0	75	2	73	\$ 561	\$ 561	\$ -	\$ 20,000	5	Desk top review	Poor	4.0	1.3	5.2			
0233	Infrastructure	Water Mains	Water Mains	KNOX AVE	BRUNETTE RD	LAIDLAW ST	150	DUCTILE IRON	53.0	1985	50	22	75	47	28	\$ 6,255	\$ 3,503	\$ 2,752	\$ 20,000	2	Desk top review	Good	2.0	1.3	2.6			
0231	Infrastructure	Water Mains	Water Mains	KZNARIC ST	QUEEN ST	KING ST	200	DUCTILE IRON	48.8	1935	50	0	75	0	78	\$ 534	\$ 534	\$ -	\$ 20,000	5	Desk top review	Poor	4.0	1.6	6.4			
0230	Infrastructure	Water Mains	Water Mains	KZNARIC ST	DUKE ST	PRINCESS ST	150	DUCTILE IRON	88.4	1935	50	0	75	0	78	\$ 829	\$ 829	\$ -	\$ 30,000	5	Desk top review	Poor	4.0	1.3	5.2			
0229	Infrastructure	Water Mains	Water Mains	KZNARIC ST	EARL ST	DUKE ST	150	DUCTILE IRON	88.4	1935	50	0	75	0	78	\$ 829	\$ 829	\$ -	\$ 30,000	5	Desk top review	Poor	4.0	1.3	5.2			
0232	Infrastructure	Water Mains	Water Mains	KZNARIC ST	MARQUIS ST	EARL ST	150	DUCTILE IRON	91.4	1935	50	0	75	0	78	\$ 858	\$ 858	\$ -	\$ 30,000	5	Desk top review	Poor	4.0	1.3	5.2			
0135	Infrastructure	Water Mains	Water Mains	KZNARIC ST	PRINCESS ST	QUEEN ST	150	DUCTILE IRON	88.4	1935	50	0	75	0	78	\$ 829	\$ 829	\$ -	\$ 30,000	5	Desk top review	Poor	4.0	1.3	5.2			
0134	Infrastructure	Water Mains	Water Mains	KZNARIC ST	LAFFIN CRES	LAFFIN CRES	150	PVC	121.9	2002	50	39	75	64	11	\$ 25,184	\$ 5,540	\$ 19,643	\$ 40,000	1	Desk top review	Very Good	1.0	1.3	1.3			
0630	Infrastructure	Water Mains	Water Mains	LAIDLAW ST	LAIDLAW ST	LAFFIN CRES	150	DUCTILE IRON</																				

City of Timmins
2014 Asset Management Plan
Watermains

Basic Asset/Component Information															Financial Accounting Values			Condition / Performance and Risk Assessment Information								Infrastructure Assets Required to Improved System Performance	
ID #	Category	Sub-Category	Department	Street	From	To	Diameter (mm)	Type	Length (m)	Year of Acquisition	PSAB U Life	PSAB Remaining UL	Useful Life	Remaining Useful Life	Age	Historical Cost December 31, 2012	Accumulated Amortization December 31, 2012	Net Book Value December 31, 2012	Replacement Cost	Condition Rating	Method of Last Condition Assessment	Asset Conditions / Deficiencies	Probability of Failure	Consequence of Failure	Risk / Criticality		Critical Maintenance Activities / Immediate Replacement
0378	Infrastructure	Water Mains	Water Mains	MARTIN AVE	SUZANNE ST	DENISE ST	150	DUCTILE IRON	295.7	1972	50	9	75	34	41	\$ 14,164	\$ 11,614	\$ 2,549	\$ 100,000	3	Desk top review	Fair		2.0	1.3	2.6	
0409	Infrastructure	Water Mains	Water Mains	MASCIOLI BLVD	J V BONHOMME BLVD	J V BONHOMME BLVD	150	DUCTILE IRON	518.2	1990	50	27	75	52	63	\$ 84,979	\$ 39,090	\$ 45,889	\$ 180,000	2	Good	Good		2.0	1.3	2.6	
0604	Infrastructure	Water Mains	Water Mains	MATTAGAMI BLVD	WILSON AVE	BELANGER AVE	150	PVC	85.3	1950	50	0	75	12	63	\$ 1,518	\$ 1,518	\$ -	\$ 30,000	4	Desk top review	Fair		3.0	1.3	3.9	
0603	Infrastructure	Water Mains	Water Mains	MATTAGAMI BLVD	ALGONQUIN BLVD	WILSON AVE	150	DUCTILE IRON	70.1	1950	50	0	75	12	63	\$ 1,247	\$ 1,247	\$ -	\$ 20,000	4	Desk top review	Fair		3.0	1.3	3.9	
0035	Infrastructure	Water Mains	Water Mains	MAURICE ST	RIVERSIDE DR	CHENIER AVE	150	DUCTILE IRON	176.8	1973	50	10	75	35	40	\$ 9,241	\$ 7,393	\$ 1,848	\$ 60,000	3	Desk top review	Fair		2.0	1.3	2.6	
	Infrastructure	Water Mains	Water Mains	McBRIDE ST	RIVERSIDE DR	ST. JEAN AVE	300	PVC	527.0	2012	50	49	75	74	1	\$ 139,550	\$ 2,791	\$ 136,759	\$ 260,000	1	Desk top review	Very Good		1.0	2.4	2.4	
0008	Infrastructure	Water Mains	Water Mains	McBRIDE ST	RIVERSIDE DR	SOUTH TO END	200	DUCTILE IRON	207.3	2001	50	38	75	63	12	\$ 42,068	\$ 10,096	\$ 31,972	\$ 80,000	1	Desk top review	Very Good		1.0	1.6	1.6	
0461	Infrastructure	Water Mains	Water Mains	McBRIDE ST	MAJESTIC DR	LAWLOR ST	150	PVC	532.0	2010	50	47	75	72	3	\$ 122,360	\$ 7,342	\$ 115,018	\$ 190,000	1	Desk top review	Very Good		1.0	1.3	1.3	
0462	Infrastructure	Water Mains	Water Mains	McCHESNEY RD	AIRPORT RD	300 m SOUTH OF AUXILIA AVE	400	DUCTILE IRON	655.3	1977	50	14	75	39	36	\$ 45,974	\$ 33,101	\$ 12,873	\$ 460,000	3	Desk top review	Fair		2.0	3.5	7.0	
0400	Infrastructure	Water Mains	Water Mains	McCHESNEY RD	400 m NORTH OF VIMY AVE	VIMY AVE	200	DUCTILE IRON	310.9	1940	50	0	75	2	73	\$ 3,710	\$ 3,710	\$ -	\$ 120,000	5	Desk top review	Poor		4.0	1.6	6.4	
0400	Infrastructure	Water Mains	Water Mains	McCLINTON DR	LOUISE AVE (WEST INT)	McCLINTON DR	150	DUCTILE IRON	408.4	1971	50	8	75	33	42	\$ 18,164	\$ 15,258	\$ 2,906	\$ 140,000	3	Desk top review	Fair		2.0	1.3	2.6	
0169	Infrastructure	Water Mains	Water Mains	McDOUGAL AVE	GOLDRUSH ST	GLENN AVE	150	DUCTILE IRON	237.7	1935	50	0	75	0	78	\$ 2,231	\$ 2,231	\$ -	\$ 80,000	5	Desk top review	Poor		4.0	1.3	5.2	
0289	Infrastructure	Water Mains	Water Mains	McINTYRE RD	FATHER COSTELLO DR	McINTYRE ARENA	150	DUCTILE IRON	182.9	1935	50	0	75	0	78	\$ 1,716	\$ 1,716	\$ -	\$ 60,000	5	Desk top review	Poor		4.0	1.3	5.2	
0494	Infrastructure	Water Mains	Water Mains	McLEOD ST	VIMY AVE	POINTECH RD	150	DUCTILE IRON	70.1	1940	50	0	75	2	73	\$ 717	\$ 717	\$ -	\$ 20,000	5	Desk top review	Poor		4.0	1.3	5.2	
0019	Infrastructure	Water Mains	Water Mains	MEADOW LANE	BONAVENTURE DR	SHIRLEY ST	150	DUCTILE IRON	183.0	1993	50	30	75	58	20	\$ 28,746	\$ 11,498	\$ 17,248	\$ 60,000	2	Desk top review	Good		2.0	2.0	2.0	
0493	Infrastructure	Water Mains	Water Mains	MELROSE BLVD	JUBILEE AVE	SOUTHERLY	150	DUCTILE IRON	189.0	1940	50	0	75	2	73	\$ 1,933	\$ 1,933	\$ -	\$ 70,000	5	Desk top review	Poor		4.0	1.3	5.2	
	Infrastructure	Water Mains	Water Mains	MICHELANO DR	HWY 655	BERRIDALE RD	150	PVC	57.0	2010	50	47	75	72	3	\$ 44,112	\$ 2,647	\$ 41,465	\$ 20,000	1	Desk top review	Good		1.0	1.3	1.3	
0185	Infrastructure	Water Mains	Water Mains	MICHENER BLVD	CLEMENT ST	RENISON AVE	150	DUCTILE IRON	216.4	1975	50	12	75	37	38	\$ 14,419	\$ 10,959	\$ 3,461	\$ 80,000	3	Desk top review	Fair		2.0	1.3	2.6	Twin existing watermain with a 200mm WM within the next 5 to 10 years to ensure security of supply.
0586	Infrastructure	Water Mains	Water Mains	MIDDLETON AVE	ONR (ROW)	MOUNTJOY ST	150	DUCTILE IRON	560.8	1977	50	14	75	39	36	\$ 36,318	\$ 26,149	\$ 10,169	\$ 200,000	3	Desk top review	Fair		2.0	1.3	2.6	
0249	Infrastructure	Water Mains	Water Mains	MILDRED AVE	DIXON ST	KING ST	150	DUCTILE IRON	88.4	1987	50	24	75	49	26	\$ 12,310	\$ 6,401	\$ 5,909	\$ 30,000	2	Desk top review	Good		2.0	1.3	2.6	
0303	Infrastructure	Water Mains	Water Mains	MINERS AVE	ENNIS ST	DELOST ST	150	DUCTILE IRON	164.6	1935	50	0	75	0	78	\$ 1,544	\$ 1,544	\$ -	\$ 60,000	5	Desk top review	Poor		4.0	1.3	5.2	
0633	Infrastructure	Water Mains	Water Mains	MOUNTJOY ST	MOUNTJOY ST	BIRCH ST	150	DUCTILE IRON	240.8	1975	50	12	75	37	38	\$ 16,044	\$ 12,194	\$ 3,851	\$ 80,000	3	Desk top review	Fair		2.0	1.3	2.6	
0363	Infrastructure	Water Mains	Water Mains	MONETA AVE	ONTARIO HYDRO (ROW)	JAMES REID RD	50	GALV STEEL	560.8	1940	50	0	75	2	73	\$ 5,737	\$ 5,737	\$ -	\$ 160,000	5	Desk top review	Poor		4.0	1.0	4.0	
	Infrastructure	Water Mains	Water Mains	MONETA AVE	ONTARIO HYDRO (ROW)	VIPOND RD	450	DUCTILE IRON	292.5	1983	50	20	75	45	30	\$ 37,275	\$ 22,365	\$ 14,910	\$ 260,000	2	Desk top review	Good		2.0	4.2	8.4	
	Infrastructure	Water Mains	Water Mains	MONETA AVE	ONTARIO HYDRO (ROW)	VIPOND RD	450	DUCTILE IRON	850.0	1984	50	21	75	46	29	\$ 111,511	\$ 64,676	\$ 46,835	\$ 770,000	2	Desk top review	Good		2.0	4.2	8.4	
	Infrastructure	Water Mains	Water Mains	MONETA AVE	PINE ST	ONTARIO HYDRO (ROW)	150	DUCTILE IRON	295.7	1970	50	7	75	32	43	\$ 12,097	\$ 10,403	\$ 1,694	\$ 100,000	3	Desk top review	Fair		2.0	1.3	2.6	Twin existing watermain with a 300mm WM within 1 year to ensure security of supply
	Infrastructure	Water Mains	Water Mains	MONETA AVE	ELM ST	BIRCH ST	150	DUCTILE IRON	200.0	1973	50	10	75	35	40	\$ 10,455	\$ 8,364	\$ 2,091	\$ 70,000	3	Desk top review	Fair		2.0	1.3	2.6	
	Infrastructure	Water Mains	Water Mains	MONETA AVE	BIRCH ST	CEDAR ST	150	DUCTILE IRON	186.0	1985	50	22	75	47	28	\$ 21,953	\$ 12,294	\$ 9,659	\$ 70,000	2	Desk top review	Good		2.0	1.3	2.6	
0437	Infrastructure	Water Mains	Water Mains	MONT SACRE COEUR (ROW)	MONT SACRE COEUR	HENDRY AVE	150	DUCTILE IRON	79.2	1940	50	0	75	2	73	\$ 811	\$ 811	\$ -	\$ 30,000	5	Desk top review	Poor		4.0	1.3	5.2	
0591	Infrastructure	Water Mains	Water Mains	MONTGOMERY AVE	CAMERON ST	MOUNTJOY ST	150	DUCTILE IRON	527.3	1940	50	0	75	2	73	\$ 5,394	\$ 5,394	\$ -	\$ 180,000	5	Desk top review	Poor		4.0	1.3	5.2	
	Infrastructure	Water Mains	Water Mains	MOORE ST	BRUCE AVE	QUEBEC AVE	450	DUCTILE IRON	235.0	1980	50	17	75	42	33	\$ 23,231	\$ 15,332	\$ 7,898	\$ 210,000	3	Desk top review	Fair		2.0	4.2	8.4	
	Infrastructure	Water Mains	Water Mains	MOORE ST	BROADWAY AVE	BRUCE AVE	350	DUCTILE IRON	393.0	1980	50	17	75	42	33	\$ 44,399	\$ 29,304	\$ 15,096	\$ 240,000	3	Desk top review	Fair		2.0	2.9	5.8	
0146	Infrastructure	Water Mains	Water Mains	MOORE ST	BRUCE AVE	TISDALE RESERVOIR	300	DUCTILE IRON	4,225.0	1948	50	0	75	10	65	\$ 91,443	\$ 91,443	\$ -	\$ 2,110,000	4	Desk top review	Fair		3.0	2.4	7.2	
	Infrastructure	Water Mains	Water Mains	MOORE ST	WILLIAM AVE	BROADWAY AVE	300	DUCTILE IRON	400.0	1980	50	17	75	42	33	\$ 45,190	\$ 29,825	\$ 15,3									

City of Timmins
2014 Asset Management Plan
Watermains

Basic Asset/Component Information																Financial Accounting Values			Condition / Performance and Risk Assessment Information										Infrastructure Assets Required to Impaired System Performance
ID #	Category	Sub-Category	Department	Street	From	To	Diameter (mm)	Type	Length (m)	Year of Acquisition	PSAB U Life	PSAB Remaining UL	Useful Life	Remaining Useful Life	Age	Historical Cost December 31, 2012	Accumulated Amortization December 31, 2012	Net Book Value December 31, 2012	Replacement Cost	Condition Rating	Method of Last Condition Assessment	Asset Conditions / Deficiencies	Probability of Failure	Consequence of Failure	Risk / Criticality	Critical Maintenance Activities / Immediate Replacement			
0218	Infrastructure	Water Mains	Water Mains	QUEEN ST	BELLEMARE ST	BOUCHER ST	150	DUCTILE IRON	134.1	1935	50	0	75	0	78	\$ 1,258	\$ 1,258	\$ 0	\$ 50,000	5	Desk top review	Poor		4.0	1.3	5.2			
0219	Infrastructure	Water Mains	Water Mains	BOUCHER ST	WATER MAIN ST	SEGUN ST	150	DUCTILE IRON	329.0	2002	50	39	75	51	24	\$ 67,954	\$ 14,951	\$ 53,007	\$ 120,000	1	Desk top review	Good		1.0	1.3	1.3			
0631	Infrastructure	Water Mains	Water Mains	RAILWAY ST	MONETA AVE	120M SOUTH OF KNOX AVE	150	DUCTILE IRON	475.5	1989	50	26	75	51	24	\$ 76,068	\$ 36,513	\$ 39,555	\$ 170,000	2	Desk top review	Good		2.0	1.3	2.6			
0387	Infrastructure	Water Mains	Water Mains	RANDALL DR	SUZANNE ST	MORANDIN AVE	200	DUCTILE IRON	408.4	1971	50	8	75	33	42	\$ 21,191	\$ 17,801	\$ 3,391	\$ 160,000	3	Desk top review	Fair		2.0	1.6	3.2			
0388	Infrastructure	Water Mains	Water Mains	RANDALL DR	RANDALL DR	RANDALL DR	150	DUCTILE IRON	216.4	1971	50	8	75	33	42	\$ 9,624	\$ 8,084	\$ 1,540	\$ 80,000	3	Desk top review	Fair		2.0	1.3	2.6			
0407	Infrastructure	Water Mains	Water Mains	RAY CANIE BLVD	COLLEGE ST	NORTH TO END	200	DUCTILE IRON	54.9	1990	50	27	75	52	23	\$ 10,497	\$ 4,829	\$ 5,668	\$ 20,000	2	Desk top review	Good		2.0	1.6	3.2			
0498	Infrastructure	Water Mains	Water Mains	REA ST	BORDEN AVE	VIMY AVE	250	DUCTILE IRON	97.5	1940	50	0	75	2	73	\$ 1,247	\$ 1,247	\$ 0	\$ 40,000	5	Desk top review	Poor		4.0	2.0	8.0			
0496	Infrastructure	Water Mains	Water Mains	REA ST	ALGONQUIN BLVD	GEORGE AVE	150	DUCTILE IRON	877.8	1940	50	0	75	2	73	\$ 8,978	\$ 8,978	\$ 0	\$ 310,000	5	Desk top review	Poor		4.0	1.3	5.2			
0497	Infrastructure	Water Mains	Water Mains	REA ST	JADE AVE	JUBILEE AVE	150	DUCTILE IRON	91.4	1940	50	0	75	2	73	\$ 935	\$ 935	\$ 0	\$ 30,000	5	Desk top review	Poor		4.0	1.3	5.2			
0499	Infrastructure	Water Mains	Water Mains	REA ST	TONELLI ST	KENT AVE	150	DUCTILE IRON	411.5	1940	50	0	75	2	73	\$ 4,209	\$ 4,209	\$ 0	\$ 140,000	5	Desk top review	Poor		4.0	1.3	5.2			
0416	Infrastructure	Water Mains	Water Mains	REG POPE BLVD	COLLEGE ST	VICTORIA AVE	150	DUCTILE IRON	374.9	1986	50	23	75	48	27	\$ 47,005	\$ 25,383	\$ 21,622	\$ 130,000	2	Desk top review	Good		2.0	1.3	2.6			
0200	Infrastructure	Water Mains	Water Mains	REKELA ST	FERGUSON RD	DIVISION ST	150	DUCTILE IRON	359.7	1935	50	0	75	0	78	\$ 3,375	\$ 3,375	\$ 0	\$ 130,000	5	Desk top review	Fair		4.0	1.3	5.2			
0196	Infrastructure	Water Mains	Water Mains	REMEMBRANCE ST	HENRY ST	FLORENCE ST	150	DUCTILE IRON	85.3	1935	50	0	75	0	78	\$ 801	\$ 801	\$ 0	\$ 30,000	5	Desk top review	Fair		4.0	1.3	5.2			
0028.1	Infrastructure	Water Mains	Water Mains	RENAISSANCE PLACE	900M N of Shirley	Northerly	300	PVC	260.0	2011	50	48	75	73	2	\$ 66,144	\$ 2,646	\$ 63,498	\$ 130,000	1	Desk top review	Good		1.0	2.4	2.4			
0028	Infrastructure	Water Mains	Water Mains	RENAISSANCE SCHOOL	SHIRLEY ST	WEST TO END	200	DUCTILE IRON	213.4	2000	50	37	75	62	13	\$ 48,381	\$ 12,579	\$ 35,802	\$ 90,000	2	Desk top review	Good		1.0	1.6	1.6			
0368	Infrastructure	Water Mains	Water Mains	RENEE PLACE	KELLY YANN DRIVE	LOZANNE CRES	200	DUCTILE IRON	158.5	1990	50	27	75	52	23	\$ 30,326	\$ 13,950	\$ 16,376	\$ 60,000	2	Desk top review	Good		2.0	1.6	3.2			
0367	Infrastructure	Water Mains	Water Mains	RENEE PLACE	KELLY YANN DRIVE	LOZANNE CRES	150	DUCTILE IRON	152.4	1990	50	27	75	52	23	\$ 24,994	\$ 11,497	\$ 13,497	\$ 50,000	2	Desk top review	Good		2.0	1.3	2.6			
0187	Infrastructure	Water Mains	Water Mains	RENISON AVE	MICHENER BLVD	CLEMENT ST	150	DUCTILE IRON	356.6	1975	50	12	75	37	38	\$ 23,762	\$ 18,059	\$ 5,703	\$ 120,000	3	Desk top review	Fair		2.0	1.3	2.6			
0413	Infrastructure	Water Mains	Water Mains	RHEAUME CRES	SHUB AVE	MORANDIN AVE	150	DUCTILE IRON	249.9	1973	50	10	75	35	40	\$ 13,065	\$ 10,452	\$ 2,613	\$ 90,000	3	Desk top review	Fair		2.0	1.3	2.6			
0034	Infrastructure	Water Mains	Water Mains	RICHARD CRES	SHIRLEY ST	MAURICE ST	150	DUCTILE IRON	265.2	1973	50	10	75	35	40	\$ 13,862	\$ 11,090	\$ 2,772	\$ 90,000	3	Desk top review	Fair		2.0	1.3	2.6			
0422	Infrastructure	Water Mains	Water Mains	WESTMOUNT BLVD	WILKIE ST	VICTORIA AVE	150	DUCTILE IRON	210.3	1960	50	0	75	22	53	\$ 5,472	\$ 5,472	\$ 0	\$ 70,000	4	Desk top review	Fair		3.0	2.0	3.9			
0385	Infrastructure	Water Mains	Water Mains	RIVERPARK RD	HWY 629	SUZANNE ST	150	DUCTILE IRON	213.4	1972	50	9	75	34	41	\$ 10,221	\$ 8,381	\$ 1,840	\$ 70,000	3	Desk top review	Fair		2.0	1.3	2.6			
0386	Infrastructure	Water Mains	Water Mains	RIVERPARK SQUARE	RIVERPARK RD	AIRPORT RD	150	DUCTILE IRON	259.1	1972	50	9	75	34	41	\$ 12,411	\$ 10,177	\$ 2,234	\$ 90,000	3	Desk top review	Fair		2.0	1.3	2.6			
0006	Infrastructure	Water Mains	Water Mains	RIVERSIDE DR	GOVERNMENT RD	JAGUAR RD	400	PVC	1,463.0	2001	50	38	75	63	12	\$ 321,697	\$ 77,207	\$ 244,490	\$ 1,020,000	1	Desk top review	Good		1.0	3.5	3.5			
0005	Infrastructure	Water Mains	Water Mains	RIVERSIDE DR	SHIRLEY ST	GOVERNMENT RD	400	PVC	1,411.2	2002	50	39	75	64	11	\$ 315,792	\$ 69,474	\$ 246,318	\$ 990,000	1	Desk top review	Good		1.0	3.5	3.5			
0004	Infrastructure	Water Mains	Water Mains	RIVERSIDE DR	MATTAGAMI RIVER BRIDGE	JOSEPH ST	400	DUCTILE IRON	1,188.7	2000	50	37	75	62	13	\$ 308,056	\$ 80,095	\$ 227,962	\$ 830,000	1	Desk top review	Good		1.0	3.5	3.5			
0003	Infrastructure	Water Mains	Water Mains	RIVERSIDE DR	MATTAGAMI RIVER BRIDGE	GOVERNMENT RD	300	DUCTILE IRON	3,261.4	1973	50	10	75	35	40	\$ 213,108	\$ 170,486	\$ 42,622	\$ 1,630,000	4.5	Desk top review	Poor		4.0	2.4	9.6	Condition rating revised to reflect the very poor condition of a 1 km section of the WM. This section should be replaced within the next 3 to 5 years at an approximate cost of \$700,000.		
0010	Infrastructure	Water Mains	Water Mains	ROBLIN ST	RIVERSIDE DR	LAWLOR AVE	150	DUCTILE IRON	283.5	1978	50	15	75	40	35	\$ 19,595	\$ 13,717	\$ 5,879	\$ 100,000	3	Desk top review	Fair		2.0	1.3	2.6			
	Infrastructure	Water Mains	Water Mains	ROBLIN ST	RIVERSIDE DR	LAWLOR AVE	150	DUCTILE IRON	283.5	1981	50	18	75	43	32	\$ 27,424	\$ 17,551	\$ 9,873	\$ 100,000	3	Desk top review	Fair		2.0	1.3	2.6			
0421	Infrastructure	Water Mains	Water Mains	ROCHDALE ST	WESTMOUNT BLVD	VICTORIA AVE	150	DUCTILE IRON	210.3	1960	50	0	75	22	53	\$ 5,472	\$ 5,472	\$ 0	\$ 70,000	4	Desk top review	Fair		3.0	1.3	3.9			
0420	Infrastructure	Water Mains	Water Mains	ROCHDALE ST (ROW)	WESTMOUNT BLVD	VICTORIA AVE	150	DUCTILE IRON	210.3	1960	50	0	75	22	53	\$ 5,472	\$ 5,472	\$ 0	\$ 70,000	4	Desk top review	Fair		3.0	1.3	3.9			
0435	Infrastructure	Water Mains	Water Mains	ROCHE AVE	TAMARACK ST	EAST TO END	150	DUCTILE IRON	70.1	1990	50	0	75	22	53	\$ 1,824	\$ 1,824	\$ 0	\$ 20,000	4	Desk top review	Fair		3.0	1.3	3.9			
0577	Infrastructure	Water Mains	Water Mains	ROCHESTER AVE	TOKE ST	LAKESHORE RD	150	DUCTILE IRON	94.0	1975	50	12	75	37	38	\$ 8,390	\$ 6,380	\$ 2,015	\$ 50,000	3	Desk top review	Fair		4.0	2.0	3.9			
0576	Infrastructure	Water Mains	Water Mains	ROCHESTER AVE	TOKE ST	LAKESHORE RD	150	DUCTILE IRON	76.2	1940	50	0	75																

City of Timmins
2014 Asset Management Plan
Watermains

Basic Asset/Component Information																Financial Accounting Values			Condition / Performance and Risk Assessment Information								Infrastructure Assets Required to Improve System Performance
ID #	Category	Sub-Category	Department	Street	From	To	Diameter (mm)	Type	Length (m)	Year of Acquisition	PSAB U Life	PSAB Remaining UL	Useful Life	Remaining Useful Life	Age	Historical Cost December 31, 2012	Accumulated Amortization December 31, 2012	Net Book Value December 31, 2012	Replacement Cost	Condition Rating	Method of Last Condition Assessment	Asset Conditions / Deficiencies	Probability of Failure	Consequence of Failure	Risk / Criticality	Critical Maintenance Activities / Immediate Replacement	
0052	Infrastructure	Water Mains	Water Mains	THEODORE PLACE	HUDSON CRES	SOUTH TO END	150	DUCTILE IRON	103.6	1974	50	11	75	36	39	\$ 6,501	\$ 5,071	\$ 1,430	\$ 40,000	3	Desk top review	Fair		2.0	1.3	2.6	
0500	Infrastructure	Water Mains	Water Mains	JUBILEE BLVD	VIMY AVE	THEORIAULT BLVD	250	DUCTILE IRON	734.6	1970	50	7	75	32	43	\$ 37,568	\$ 32,309	\$ 5,260	\$ 330,000	3	Desk top review	Fair		2.0	2.0	4.0	
0502	Infrastructure	Water Mains	Water Mains	THEORIAULT HIGH SCHOOL	THEORIAULT BLVD	THEORIAULT HIGH SCHOOL	150	DUCTILE IRON	381.0	1972	50	9	75	34	41	\$ 18,252	\$ 14,967	\$ 3,285	\$ 130,000	3	Desk top review	Fair		2.0	1.3	2.6	
0612	Infrastructure	Water Mains	Water Mains	THIRD AVE	MOUNTJOY ST	MAPLE ST	250	DUCTILE IRON	156.0	1998	50	35	75	60	15	\$ 34,350	\$ 10,305	\$ 24,045	\$ 70,000	1	Desk top review	Very Good		1.0	2.0	2.0	
0614	Infrastructure	Water Mains	Water Mains	THIRD AVE	BALSAM ST	SPRUCE ST	200	DUCTILE IRON	256.0	1940	50	0	75	2	73	\$ 3,055	\$ 3,055	\$ -	\$ 100,000	5	Desk top review	Poor		4.0	1.6	6.4	
0613	Infrastructure	Water Mains	Water Mains	THIRD AVE	MAPLE ST	BALSAM ST	150	DUCTILE IRON	167.6	1940	50	0	75	2	73	\$ 1,715	\$ 1,715	\$ -	\$ 60,000	5	Desk top review	Poor		4.0	1.3	5.2	
0048	Infrastructure	Water Mains	Water Mains	TIMCOR CRES	GATINEAU BLVD	GATINEAU BLVD	150	DUCTILE IRON	317.0	1976	50	13	75	38	37	\$ 20,528	\$ 15,191	\$ 5,337	\$ 110,000	3	Desk top review	Fair		2.0	1.3	2.6	
0397	Infrastructure	Water Mains	Water Mains	TIMMINS SEWAGE PLANT	AIRPORT RD	WEST TO END	150	DUCTILE IRON	457.2	1977	50	14	75	39	36	\$ 29,607	\$ 21,317	\$ 8,290	\$ 160,000	3	Desk top review	Fair		2.0	1.3	2.6	
0655	Infrastructure	Water Mains	Water Mains	TIMMINS WATER PLANT	TIMMINS WATER PLANT	BANNERMAN PARK	750	DUCTILE IRON	510.0	1983	50	20	75	45	30	\$ 139,269	\$ 83,561	\$ 55,707	\$ 970,000	2	Desk top review	Good		2.0	5.0	10.0	Replace within 3 to 5 years
0002	Infrastructure	Water Mains	Water Mains	TIMMINS WATER PLANT	TIMMINS WATER PLANT	MCCHESNEY RD	400	DUCTILE IRON	1,249.7	1960	50	0	75	22	53	\$ 43,349	\$ 43,349	\$ -	\$ 870,000	4	Desk top review	Poor		3.0	3.5	10.5	Replace within 3 to 5 years
	Infrastructure	Water Mains	Water Mains	TIMMINS WATER PLANT	TIMMINS WATER PLANT	300M SOUTH OF AUXILIA AVE	400	DUCTILE IRON	2,000.0	1977	50	14	75	39	36	\$ 140,309	\$ 101,022	\$ 39,287	\$ 1,400,000	3	Desk top review	Fair		2.0	3.5	7.0	
0001	Infrastructure	Water Mains	Water Mains	TIMMINS WATER PLANT	TIMMINS WATER PLANT	RIVERSIDE DR	250	DUCTILE IRON	207.3	1960	50	0	75	22	53	\$ 6,740	\$ 6,740	\$ -	\$ 90,000	4	Desk top review	Fair		3.0	2.0	6.0	
0654	Infrastructure	Water Mains	Water Mains	TIMMINS WATER PLANT	TIMMINS WATER PLANT	TIMMINS FUN PARK	200	DUCTILE IRON	472.4	1986	50	23	75	48	27	\$ 69,107	\$ 37,318	\$ 31,789	\$ 190,000	2	Desk top review	Good		2.0	1.6	3.2	
0653	Infrastructure	Water Mains	Water Mains	TIMMINS WATER PLANT	TIMMINS WATER PLANT	WEST ON FELDMAN RD	150	DUCTILE IRON	396.2	1985	50	22	75	47	28	\$ 46,767	\$ 26,190	\$ 20,578	\$ 140,000	2	Desk top review	Good		2.0	1.3	2.6	
0651	Infrastructure	Water Mains	Water Mains	TIMMINS WATER TOWER	TIMMINS WATER TOWER	HWY 655	300	DUCTILE IRON	428.7	1975	50	12	75	37	38	\$ 37,910	\$ 28,812	\$ 9,098	\$ 210,000	3	Desk top review	Fair		2.0	2.4	4.8	
0650	Infrastructure	Water Mains	Water Mains	TIMMINS WATER TOWER	TIMMINS WATER TOWER	ALGONQUIN BLVD	200	DUCTILE IRON	365.8	1975	50	12	75	37	38	\$ 28,433	\$ 21,609	\$ 6,824	\$ 150,000	3	Desk top review	Fair		2.0	1.6	3.2	
0093	Infrastructure	Water Mains	Water Mains	TISDALE AVE	DUNN AVE	ALMA LANE	150	DUCTILE IRON	341.4	1935	50	0	75	0	78	\$ 3,203	\$ 3,203	\$ -	\$ 120,000	5	Desk top review	Poor		4.0	1.3	5.2	
0094	Infrastructure	Water Mains	Water Mains	TISDALE AVE	DUNN AVE	SMITH AVE	100	DUCTILE IRON	158.5	1935	50	0	75	0	78	\$ 1,363	\$ 1,363	\$ -	\$ 50,000	5	Desk top review	Poor		4.0	1.1	4.4	
0324	Infrastructure	Water Mains	Water Mains	TODD AVE	DELNITE RD	HAZELNUT ST	100	DUCTILE IRON	182.9	1985	50	22	75	47	28	\$ 19,786	\$ 11,080	\$ 8,706	\$ 50,000	2	Desk top review	Good		2.0	1.1	2.2	
0459	Infrastructure	Water Mains	Water Mains	TOKE ST	HOWARD AVE	ROSS AVE	300	DUCTILE IRON	137.2	1990	50	27	75	52	23	\$ 29,993	\$ 13,797	\$ 16,196	\$ 70,000	2	Desk top review	Good		2.0	2.4	4.8	
0458	Infrastructure	Water Mains	Water Mains	60 m NORTH OF BROUSSEAU	TOKE ST	JAMES AVE	150	DUCTILE IRON	1,194.8	1990	50	27	75	52	23	\$ 195,951	\$ 90,138	\$ 105,814	\$ 420,000	2	Desk top review	Good		2.0	1.3	2.6	
0460	Infrastructure	Water Mains	Water Mains	TOKE/PATRICIA ST (LANE)	EIGHTH AVE	HOWARD AVE	250	DUCTILE IRON	435.9	1940	50	0	75	2	73	\$ 5,573	\$ 5,573	\$ -	\$ 200,000	5	Desk top review	Poor		4.0	2.0	8.0	
0594	Infrastructure	Water Mains	Water Mains	TONELLI ST	CODY AVE	ONR (ROW)	150	DUCTILE IRON	121.9	1950	50	0	75	12	63	\$ 2,169	\$ 2,169	\$ -	\$ 40,000	4	Desk top review	Fair		3.0	1.3	3.9	
0180	Infrastructure	Water Mains	Water Mains	TYNNE COURT	DANIEL CRES	FERGUSON RD	150	DUCTILE IRON	100.6	1976	50	13	75	38	37	\$ 6,514	\$ 4,820	\$ 1,694	\$ 40,000	3	Desk top review	Fair		2.0	1.3	2.6	
0179	Infrastructure	Water Mains	Water Mains	TYNNE COURT	SPILLENAR ST	EAST TO END	150	DUCTILE IRON	94.5	1976	50	13	75	38	37	\$ 6,119	\$ 4,528	\$ 1,591	\$ 30,000	3	Desk top review	Fair		2.0	1.3	2.6	
0418	Infrastructure	Water Mains	Water Mains	UNIVERSITY ST (ROW)	JUBILEE AVE	VICTORIA AVE	150	DUCTILE IRON	435.9	1960	50	0	75	22	53	\$ 11,340	\$ 11,340	\$ -	\$ 150,000	4	Desk top review	Fair		3.0	1.3	3.9	
0062	Infrastructure	Water Mains	Water Mains	VANIER ST	CENTRE ST	NORMAN ST	150	DUCTILE IRON	137.2	1981	50	18	75	43	32	\$ 13,270	\$ 8,493	\$ 4,777	\$ 50,000	3	Desk top review	Fair		2.0	1.3	2.6	
0403	Infrastructure	Water Mains	Water Mains	VICTORIA AVE	RICHELIEU ST	MACLEAN DR	400	DUCTILE IRON	292.6	1972	50	9	75	34	41	\$ 15,186	\$ 12,452	\$ 2,733	\$ 200,000	3	Desk top review	Fair		2.0	3.5	7.0	
0401	Infrastructure	Water Mains	Water Mains	VICTORIA AVE	RICHELIEU ST	DENISE AVE	250	DUCTILE IRON	652.3	1971	50	8	75	33	42	\$ 36,260	\$ 30,458	\$ 5,802	\$ 290,000	3	Desk top review	Fair		2.0	2.0	4.0	
0404	Infrastructure	Water Mains	Water Mains	VICTORIA AVE	BARTLEMAN ST	MACLEAN DR	250	DUCTILE IRON	64.0	1973	50	10	75	35	40	\$ 4,182	\$ 3,346	\$ 836	\$ 30,000	3	Desk top review	Fair		2.0	2.0	4.0	
0402	Infrastructure	Water Mains	Water Mains	VICTORIA AVE	UNIVERSITY (ROW)	MELROSE (ROW)	150	DUCTILE IRON	76.2	1971	50	8	75	33	42	\$ 3,389	\$ 2,847	\$ 542	\$ 30,000	3	Desk top review	Fair		2.0	1.3	2.6	
0487	Infrastructure	Water Mains	Water Mains	VIMY AVE	GILLIES ST	REA ST	250	DUCTILE IRON	560.8	1940	50	0	75	2	73	\$ 7,171	\$ 7,171	\$ -	\$ 250,000	5	Desk top review	Poor		4.0	2.0	8.0	
0486	Infrastructure	Water Mains	Water Mains	VIMY AVE	MACLEAN DR	WATERLOO RD	150	DUCTILE IRON	174.0	2001	50	38	75	63	12	\$ 35,317	\$ 8,476	\$ 26,841	\$ 60,000	1	Desk top review	Very Good		1.0	1.3	1.3	
0184	Infrastructure	Water Mains	Water Mains	VIOLA COURT	MICHENER BLVD	NORTH TO END	150	DUCTILE IRON	100.6	1975	50	12	75	37	38	\$ 6,702	\$ 5,093	\$ 1,608	\$ 40,000	3	Desk top review	Fair		2.0	1.3	2.6	
	Infrastructure	Water Mains	Water Mains	VIPOND RD	MONETA AVE	SHAW WELLS WATERMAIN	450	DUCTILE IRON	850.0	1984	50	21	75	46	29	\$ 111,511	\$ 64,676	\$ 46,835	\$ 770,000	2	Desk top review	Good		2.0	4.2	8.4	
0285	Infrastructure	Water Mains	Water Mains	VIPOND RD	MONETA AVE	SHAW WELLS WATERMAIN	450	DUCTILE IRON	6,480.0																		